

VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157 GOVERNOR HUNT ROAD VERNON, VERMONT 05354

> February 13, 1991 VYV #91-033

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

REFERENCE: Operating License DPR-28 Docket No. 50-271

Reportable Occurrence No. LER 90-17 Rev. 1

Dear Sirs:

As defined by 10 CFR 50.73, we are reporting the attached Reportable Occurrence as LER 90-17 Pev. 1.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Donald A. Reid Plant Manager

Regional Administrator cc: USNRC Region I 475 Allendale Road King of Prussia, PA 19406

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (6-89) LICENSEE EVENT REPORT (LER) FACILITY NAME (1) VERMONT YANKEE NUCLEAR POWER STATION TITLE (4)							E: W 5: Bi M. R: 2: P	APPROVED OMS NO.3150-0104 EXPIRES 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20603. DOCKET NO. (*) PAGE (*) O 5 O O 2 7 1 O 1 OF O 3							
12166	1-1	APRM MI	SCALIBRA	TION D	UE TO	PERSONN	EL ERR	OR							
EVENT	DATE (5)	LER N	UMBER	(6)	RE	PORT D	ATE () OT	HER FA	CILI	TIES I	NVOLV	ED (*)	
MONTH	DAY	YEAR YE	AR SE	Q. #	REV	# MONT	H DAY	YEAR		ITY NA	MES		KET N		
		0100		1 . 1 .			1.1.		N/A				0 0		
1 0 OPERAT	AND DESCRIPTION OF THE PARTY OF		O -O REPORT						and the second second second second second second		eral der		0 0		
MODE			0.402(b)			20.405(KEY MI				ONE U		3.71(b)	
POWER	1		0.405(a)			50.36(0		-		(a)(2)			7	3.71(c)	
LEVEL (10) 0	2 0 20	0.405(a)	(1)(II)		50.36(0			100	(a)(2)	7			OTHER:	
	Annual Contract of the Contrac		0.405(a)			50.73(8		1	and the same of th	(a)(2)					
*****		20	0.405(a)	(1)(1v)		50.73(8	1)(2)(1	I)	50.73	(a)(2)	(vi	ii)(B)			
	11111	20	0.405(a)			50.73(8				(a)(2)	(x)				
				LICE	ENSEE C	ONTACT	FOR TH	IS LER	(12)						
NAME												CORDONOLOGICA, PRINCIPALIS	EPHON	E NO.	
										- 4	ARI				
DONALD A. REID, PLANT MANAGER											CO		1.00	ed ed al	
DUNAL			ONE LINE		ACH COM	DONENT	EATLUE	DE DECC	DIDED I	N THIC	PE	0 2 2 5	171-1	7 7 1	
CAUSE	SYST	trape or the same of the same			RTABLE	TONENT		SYST	COMPNT			REPORT			
OROGE	0101	CONTRA	1 1111	TO N	1,010,000,000,000		UNUGE	10101	COMPA	ere		TO NPE		11111	
			-	1	1100	11111		-		-		10 141 1	100	11111	
N/A		1111					N/A		1111	111	1				
		1				X 4 9 X 4									
N/A			DIEMENT	1 0500	DT FUET	OTED				1	0.71		Tust	DI 100	
	-	SUP	PLEMENTA	L REPO	RT EXPE	CIED (14)			EXPE			MO	DA YR	
YES (If yes, complete EXPECTED SUBMISSION DATE							ATENT				SUBMISSION DATE (18)			1 1	
			1400 spa						n . mn					1363	
MDOTA	101 (1	THIT LO	Taon Sha	ces, i	.e., ap	prox.	rirceci	1 Sing	e-space	typen	n i c	Cen in	ies /		

On October 29, 1990 an engineering review of APRM (EIIS=IG) calibration data obtained during plant startup identified a miscalibration at 1156 and 1254 hours on October 16, 1990 with the plant at 20% power. The Average Power Range Monitors (APRNs) were miscalibrated lower than required in Technical Specification sections 2.1.A.1.a, 2.1.B.1 and 3.1.B.

The root cause of the miscalibration was due to personnel error on the part of the technician performing the calibrations.

The review of the calibration data and initiation of the PRO were delayed due to startup activities and unfamiliarity with the reportable occurrence process.

Corrective actions include, training in attention to detail for all members of the department involved in surveillance procedures. The department has set up a special box for Technical Specification surveillances and Supervisors are required to review these surveillances soon after completion. Department personnel involved with potentially reportable occurrence decisions have been instructed on the urgency of taking prompt actions.

NRC Form 366A U.S. NUCLEAR REGULATORY (6+89)	COMMISSION	WIT	IMATED H THIS	BU	EXPIR RDEN F FORMAT	RES PER TION	A/3 RES	C/92 PONSE LLECT:	TO C	REQUE	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION		BURDEN ES MANAGEMEN REGULATOR 20555, AN PROJECT (O HRS. FORWARD COMMENTS REGARDING DEN ESTIMATE TO THE RECORDS AND REPORMANCE BRANCH (P-530), U.S. NUCLEAR BULATORY COMMISSION, WASHINGTON, DC B5, AND TO THE PAPERWORK REDUCTION BJECT (3160-0104), OFFICE OF MANAGEMEN BUDGET, WASHINGTON, DC 20603.					
UTILITY NAME (1)	DOCKET NO.	Button to the party of the		market and the said	NUMBE		on a constitution of		Company of the last	AGE	(3)
			YEAR	decourse	SEQ.		-	REV#			
VERMONT YANKEE NUCLEAR POWER STATION	0 5 0 0 0 0 2	7 1	9 0	-	0 1	17	-	0 1	0 2	OF	01

TEXT (If more space is required, use additional NRC Form 366A) (17)

DESCRIPTION OF EVENT

On October 29, 1990 an engineering review of "APRM Calibration Check Off Sheets" performed during the startup from the refueling outage was performed. This review identified that at 1156 and 1254 hours on October 16, 1990 the Average Power Range Monitors (APRMs) were inadvertently calibrated lower than required by Technical Specification sections 2.1.A.1.a, 2.1.B.1, and 3.1.B. At the time of the event the plant was starting up from a six week refueling outage with power at approximately 20% reactor power.

On November 14, 1990, after a review of the occurrence by Reactor Engineering it was determined that the event could potentially be reportable and a Potential Reportable Occurrence (PRO) was initiated.

Technical Specifications require that above 1% Core Thermal Power (CTP) the ratio of Core Maximum Fraction of Limiting Power Density (CMFLPD) to Fraction of Rated Power (FRP) referred to as (MOPRAT) be less than 1.0. This ensures that CMFLPD remains below 1.0 should power inadvertently reach 100% (FRP=1.0). Maintaining CMFLPD less than 1.0 ensures the fuel cladding incurs less than 1% plastic strain during operational transients and prevents the clad from failing.

Procedure OP 4400 provides instructions for APRM gain adjustment. The value of MOPRAT was taken from the last core parameters computer (3D Monicore Monitor) case. MOPRAT is inverted to a Gain Adjustment Factor (GAF) which is used to raise the APRM reading above the actual CTP. The table below provides the details of both events.

Date/Time	HEAT BALANCE % CTP	MOPRAT	DESIRED APRM % CTP	ADJUSTED APRM % CTP	MAX. ERROR % CTP
10/16/90 1156 10/16/90 1254	18.96 21.95	1.372	26.0 32.3	25.4 30.9	0.6

After the second event on 10/16/90 at 1254 hours, reactor power was held constant until 2015 hours. From a computer calculation of CTP taken at 1847 hours only one of the six APRMs were still out of specification by 0.2% CTP. The next calibration was performed at 0447 hours on 10/17/90 at 48% CTP in which the MOPRAT used was 1.221. This calibration and all further calibrations were performed correctly.

CAUSE OF EVENT

Personnel error was the cause of the event. Procedure OP 4400 is clear as to how the APRMs are to be calibrated. The technician did not have a copy of the procedure but was using the appropriate data sheet, which clearly states the acceptance criterion. The checkoff sheet requires a written verification that all APRM final readings are adjusted to be +2%/-0% of the desired value. These reviews were performed incorrectly twice, on October 16, 1990.

NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO.3150-0104 (6489) EXPIRES 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE PECORDS AND REPORTS LICENSEE EVENT REPORT (LER) TEXT CONTINUATION MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20603. LER NUMBER (6) UTILITY NAME (1) DOCKET NO. (2) PAGE (3) YEAR SEQ. # VERMONT YANKEE NUCLEAR POWER STATION | 0 5 0 0 0 2 7 1 9 0 - 0 1 7 - 0 1 0 3 0F 0 4 TEXT (If more space is required, use additional NRC Form 366A) (17)

The technician who made the error had performed this calibration many times over the previous 13 years and is aware that the final readings must be $\pm 2/-0\%$ of the adjusted value. The last time he calibrated the APRMs was in August of 1990.

The subsequent review conducted on October 29, 1990 which identified the error is normally conducted within two days of the calibration. However in this case the review occurred twelve days after the miscalibration due to heavy manpower requirements involved with Plant startup. The reviewer immediately documented the event to his immediate supervisor. The reviewer also had a discussion with the technician, pointing out his error and reminding him of the correct acceptance criterion.

The initiation of a PRO evaluation was delayed until November 14, 1990 because the Reactor Engineering Department was conducting their own internal engineering evaluation process to determine whether the event was reportable. This evaluation was conducted over a two week period and concluded that the event would be reportable, therefore the PRO evaluation process was initiated on November 14, 1990. This PRO evaluation agreed with the Reactor Engineering conclusion and a Licensee Event Report was submitted.

ANALYSIS OF EVENT

The requirements of Tech. Spec. sections 2.1.A.1.a, 2.1.B.1 and 3.1.B were not satisfied in that, the open gains were not applied to the APRMs. However, no Tech. Spec. Limiting Safety System Setting (LSSS) was violated due to conservatism present in the APRM rod block and scram setpoints. There was approximately 4% conservatism in both the APRM rod block and scram setpoints at the time of the event. This extra margin is present due to the conservatism in setpoint adjustments and flow inputs into the APRM flow bias rod block and scram lines.

Had a transient occurred a full reactor scram would have been completed before CMFLPD reached 1.0. Therefore, no fuel failures would have developed in the event of an operational transient. As a result the event did not or would not have had any adverse safety implications to public health and safety.

Even though operators were unaware of the miscalibration, normal practice is to take actions which bring MOPRAT back to 1.0 by core flow increases and control rod withdrawal. This was confirmed by the MOPRAT used for the next calibration at 0447 hours the next day.

The review of these surveillances were late due to manpower constraints during plant startup activities. Normally surveillances are reviewed within two working days of completion.

The initiation of a Potential Reportable Occurrence was not performed until November 14, 1990 by Reactor Engineering personnel.

NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (6-89)

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

APPROVED OMS NO.3150-0104 EXPIRES 4/30/92

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20603.

UTILITY NAME (1)

DOCKET NO. (2)

YEAR SEQ. # PEV#

VERMONT YANKEE NUCLEAR POWER STATION 0 5 0 0 0 2 7 1 9 0 - 0 1 7 - 0 1 0 4 0F 0 4
TEXT (If more space is required, use additional NRC Form 366A) (17)

CORRECTIVE ACTIONS

No corrective actions were taken during the event, the deviation was not discovered until the review/verification process after the reactor was at full power.

All members of the department involved in surveillance procedures have received training in the techniques of attention to detail.

All Tech. Spec. surveillances will be reviewed in a timely manner. The department has set up a special box for Tech. Spec. surveillances and supervisors are required to review these surveillances soon after completion.

Personnel involved in deciding on whether an event is potentially reportable have been instructed on the urgency of initiating a Potential Reportable Occurrence evaluation to allow for a timely decision regarding reportability.

ADDITIONAL INFORMATION

No similar event has occurred at this facility.