

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ][ ][ ][ ][ ] 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G | A | E | I | H | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 0 | 5

01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 1 | 1 | 2 | 0 | 7 | 9 | 8 | 1 | 1 | 3 | 0 | 8 | 2 | 9

02 | While performing the "SUPPRESSION CHAMBER TO DRYWELL VACUUM BREAKER SYS-  
03 | TEM OPERABILITY" procedure, the "E" Vacuum Breaker failed to open as  
04 | required by Tech. Specs. 4.6.4.1.A. The aforementioned procedure was  
05 | then immediately performed on the remaining operable vacuum breakers  
06 | per Tech. Specs. 3.6.4.1, ACTION a. The health and safety of the  
07 | public were not affected by this non-repetitive event.

09 | S | A | E | B | V | A | L | V | E | X | X | C | LER/RO REPORT NUMBER 79, ACTION TAKEN BZ, EFFECT ON PLANT Z, SHUTDOWN METHOD Z, HOURS 0000, ATTACHMENT SUBMITTED N, NRPD-4 FORM SUB. N, PRIME COMP. SUPPLIER N, COMPONENT MANUFACTURER G202

10 | The cause of the event has been attributed to a stuck valve operator.  
11 | The valve operator was freed and repaired. The "E" Torus/Drywell Vacuum  
12 | Breaker was then satisfactorily function tested per the "SUPPRESSION  
13 | CHAMBER TO DRYWELL VACUUM BREAKER SYSTEM OPERABILITY" procedure and was  
14 | returned to service.

15 | E | 090 | NA | B | Operator Observation  
16 | Z | Z | NA | NA  
17 | 000 | Z | NA  
18 | 000 | NA  
19 | Z | NA  
20 | N | NA  
21 | 8212140436 821130 PDR ADOCK 05000366 S PDR