

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G | A | E | I | H | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 1 | 7 | 1 | 2 | 0 | 2 | 8 | 1 | 8 | 1 | 2 | 0 | 7 | 8 | 2 | 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | A surveillance test on the HPCI Steam Line Pressure Switches showed the  
03 | N001D switch to actuate at 106 psig. Tech. Specs. Section 3.2-2, item 10  
04 | requires actuation at >= 100 psig, which with the +7.3 psig head  
05 | correction corresponds to an instrument reading of 107.3 psig. Plant  
06 | operation was not affected by this event. The health and safety of the  
07 | public were not affected by this repetitive event (last reported on  
08 | LER 50-321/1981-109).

09 | I | B | 11 | E | 12 | G | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16  
7 8 9 10 11 12 13 18 19 20  
17 | 8 | 1 | 21 | 22 | 1 | 3 | 1 | 24 | 26 | 0 | 3 | 28 | 29 | X | 30 | 1 | 32  
18 | E | 18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | N | 25 | B | 0 | 6 | 9 | 26  
7 8 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this event has been attributed to setpoint drift. The  
11 | Barksdale Pressure switches were recalibrated, successfully functionally  
12 | tested, and returned to service. Design changes will be implemented as  
13 | necessary.

15 | E | 28 | 0 | 8 | 2 | 29 | NA | 30 | B | 31 | Surveillance Test | 32  
7 8 9 10 12 11 44 45 46 80

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
7 8 9 10 11 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
7 8 9 11 12 13 80

18 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 11 12 80

19 | Z | 42 | NA | 43  
7 8 9 10 80

20 | N | 44 | NA | 45 | 8212150011 821207  
PDR ADOCK 05000321  
S PDR  
NRC USE ONLY  
68 69 90

NAME OF PREPARER S. B. Tipps

PHONE (912) 367-7851