



NRRC REGION II  
ATLANTA, GEORGIA  
DEC 13 AIO: 34

**Florida  
Power**  
CORPORATION

December 7, 1982  
#3F-1282-03  
File: 3-0-3-a-1

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
101 Marietta Street N.W., Suite 3100  
Atlanta, Ga. 30303

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
Licensee Event Report No. 82-070

Dear Mr. O'Reilly:

Enclosed please find Licensee Event Report No. 82-070 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.9.b.

Very truly yours,

G. R. Westafer  
Manager  
Nuclearing Licensing and Fuel Management

PGH/mlg

Enclosure

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

IE2.  
OFFICIAL COPY  
82-22

8212150099 821207  
PDR ADOCK 05000302  
S PDR

## SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-070/03L-0  
FACILITY: Crystal River Unit #3  
REPORT DATE: December 7, 1982  
OCCURRENCE DATE: November 7, 1982

### IDENTIFICATION OF OCCURRENCE:

Channel "B" of the Nuclear Overpower Instrumentation, a Reactor Protection System, was inoperable. Technical Specification 3.3.1.1. requires initiation of Action Statement Two with one of the four Nuclear Overpower Channels inoperable.

### CONDITIONS PRIOR TO OCCURRENCE:

MODE 1 (69% Full Power).

### DESCRIPTION OF OCCURRENCE:

At 0734 on November 7, 1982, Reactor Coolant Flow Transmitter (RC-14A-FT2) failed. Failure of the transmitter caused Channel "B" of the Nuclear Overpower Instrumentation to be inoperable. Channel "B" was verified in the tripped condition. The minimum channels operable requirement was met; Channels A, C, and D were available. The Quadrant Power Tilt was monitored ever 8 hours. Both transmitters in Channel "B" were recalibrated. During calibration operations, the companion flow transmitter (RC-14B-FT2) sustained damage. Channel was restored to operability at 1500 on November 9, 1982.

### DESIGNATION OF APPARENT CAUSE:

The failure of RC-14A-FT2 was caused by a shorted capacitor in the transmitter power supply. The failure of RC-14B-FT2 was caused by inoperable bellows. At this time, it is believed that the bellows failed due to improperly isolating the transmitter to perform a channel calibration.

### ANALYSIS OF OCCURRENCE:

There was no effect on public health or safety. Nuclear Overpower Channels A, C, and D were operable to provide the necessary trip function.

### CORRECTIVE ACTION:

The capacitor and bellows were replaced, the channel was recalibrated and functionally tested satisfactorily.

### FAILURE DATA:

This is the fourth failure for Channel "B" and the twentieth report under Technical Specification 3.3.1.1.