

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 82036 Technical Specification Involved 3.8.B.8

Reported Under Technical Specification 6.7.2.b.(2) * Date Due NRC 12/13/82

Event Narrative:

Unit 1 was operating at 100-percent power, unit 2 was in a refueling outage, and unit 3 was operating at 82-percent power. Only unit 2 was affected by the event. While in a refueling outage, the reactor building continuous air monitor (CAM) 2-90-250 was disabled due to a broken drive belt on the air sampling pump. The event was discovered by an assistant unit operator when he noticed the control room recorder pens acting erratically. Upon investigation, the broken drive belt was discovered.

Technical Specification 3.8.B.8 requires this vent to be continuously monitored whenever in service. Upon notification, the radiochemical lab began collecting hourly grab samples and all activity levels were found to be within technical specification limits. There was no effect on public health or safety. The belt was replaced and the CAM put back in service approximately eight hours after discovery.

The drive belt and failure are considered to have been caused by normal wear and no recurrence control is required. The drive belts are checked periodically as specified by Surveillance Instruction 4.8.B.4.A.2.

* Previous Similar Events:

BFRO 50-259/82008, 82061
296/81063, 81067

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP