

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

⑦ ⑧ ⑨ F L C I R P I ⑭ ⑮ 3 0 1 0 - 1 0 0 0 0 0 - 0 0 ⑲ ⑳ 4 1 1 1 1 ㉑ ㉒ 4 ㉓ ㉔ 5

CON'T

⑦ ⑧ ⑨ 0 1 ㉕ ㉖ L ㉗ ㉘ 6 0 5 0 - 0 3 0 2 ㉙ ㉚ 7 1 1 1 4 8 2 ㉛ ㉜ 8 1 2 0 7 8 2 ㉝ ㉞ 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

⑦ ⑧ ⑨ 0 2 At 1300, during normal operation, Radiation Monitoring Instrument RM-A5,
⑩ Control Room Iodine Channel, was inoperable contrary to T.S. 3.3.3.1.
⑪ Control Room Ventilation was placed in recirculation and maintenance
⑫ was initiated. Operability was restored on 11-14-82. There was no
⑬ effect upon the public health or safety. This is the second event
⑭ for this radiation monitor and the eight report under Technical
⑮ Specification 3.3.3.1.

⑦ ⑧ ⑨ 0 9 ㉟ ㊱ B A ㊲ ㊳ E ㊴ ㊵ F ㊶ ㊷ I N S T R U ㊸ ㊹ S ㊺ ㊻ Z ㊼ ㊽ 0

⑦ ⑧ ⑨ 0 1 ㊾ ㊿ 8 2 ㋀ ㋁ 0 1 7 1 ㋂ ㋃ 0 1 3 ㋄ ㋅ L ㋆ ㋇ 0

⑦ ⑧ ⑨ 0 1 ㋈ ㋉ A ㋊ ㋋ Z ㋌ ㋍ Z ㋎ ㋏ 0 0 0 0 ㋐ ㋑ Y ㋒ ㋓ N ㋔ ㋕ A ㋖ ㋗ 1 3 0 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉟

⑦ ⑧ ⑨ 1 0 The cause of this event is attributed to a failed rotary selector switch.
⑩ The rotary selector switch was replaced and the radiation monitor
⑪ functionally checked satisfactorily.
⑫
⑬

⑦ ⑧ ⑨ 1 5 ㋘ ㋙ E ㋚ ㋛ 0 9 7 ㋜ ㋝ NA ㋞ ㋟ NA ㋠ ㋡ Operator Observation

⑦ ⑧ ⑨ 1 6 ㋢ ㋣ Z ㋤ ㋥ Z ㋦ ㋧ NA ㋨ ㋩ NA

⑦ ⑧ ⑨ 1 7 ㋪ ㋫ 0 0 0 ㋬ ㋭ Z ㋮ ㋯ NA

⑦ ⑧ ⑨ 1 8 ㋰ ㋱ 0 0 0 ㋲ ㋳ NA

⑦ ⑧ ⑨ 1 9 ㋴ ㋵ Z ㋶ ㋷ NA

⑦ ⑧ ⑨ 2 0 ㋸ ㋹ N ㋺ ㋻ NA

NAME OF PREPARER C. G. Brown

PHONE: 904/795-6486

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-071/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: December 7, 1982

OCCURRENCE DATE: November 14, 1982

IDENTIFICATION OF OCCURRENCE:

Control Room Iodine Activity Monitor, RM-A5, was inoperable. Technical Specification 3.3.3.1. requires that this Radiation Monitoring Instrument be operable in all modes.

CONDITIONS PRIOR TO OCCURRENCE:

MODE 1 (97% Full Power).

DESCRIPTION OF OCCURRENCE:

At 1300, on November 14, 1982, RM-A5 was determined to be inoperable. The Control Room ventilation system was placed in the recirculation mode, and maintenance was initiated. Operability was restored on November 14, 1982.

DESIGNATION OF APPARENT CAUSE:

This failure was caused by a faulty rotary selector switch on the control panel of RM-A5.

ANALYSIS OF OCCURRENCE:

There was no effect on public health or safety.

CORRECTIVE ACTION:

The switch was replaced, and the radiation monitor was functionally checked satisfactorily.

FAILURE DATA:

This is the second time RM-A5 failed and the eighth report under Technical Specification 3.3.3.1.