

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 A L B R F 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5

1 L 5 0 0 0 2 9 6 7 1 1 1 1 8 2 3 1 2 0 9 8 2 5

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

1 During normal operation, while performing daily background source check of the
2 3-90-251 turbine building CAM, the inlet hose was found disconnected. For a period
3 of up to 24 hours, the turbine building roof vents were not monitored as required by
4 T.S. 3.8.B.8. SI 4.8.B.1.a.1 (CAMs) indicated no significant releases during this
5 period. There was no effect on public health or safety. There are no redundant
6 systems.

M C	11	X	13	Z 13	Z Z Z Z Z Z	14	Z 15	Z 16
17 8 2	21 22	23	24 25 26	27	28 29	30 31	32 33	34 35 36 37
33 34	35 36	37 38 39 40	41 42	43 44	45 46 47	48 49	50 51 52 53	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 It is possible the event resulted from the failure of the quick disconnect fittings
2 to be securely latched. Instructions have been given to all laboratory analysts
3 to ensure all hose connections are checked to ensure they latch.

E	1 0 0	30	B 31	Radiochemical analyst observation
33 34	35			
33 34	35			
33 34	35			
33 34	35			
33 34	35			

N 1 8212150111 821209
S PDR ADOCK 05000296 PDR

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 82053 Technical Specification Involved 3.8.B.8

Reported Under Technical Specification 6.7.2.b.(2) Date Due NRC 12/10/82

Event Narrative:

Unit 1 was operating at 100-percent power, unit 2 was in a refueling outage, and unit 3 was operating at 100-percent power. Only unit 3 was affected by the event. During normal operation, while performing daily background and source check on 3-90-251 CAM, the inlet hose was discovered to be disconnected. Technical Specification 3.8.B.8 requires that the turbine building roof vents be monitored when in service. This was not done for up to 24 hours. SI 4.8.B.1.a.1 indicated no significant releases during this period of any CAM including a CAM monitoring adjacent roof vents. There are no redundant systems.

The cause of the event is believed to be the failure of the quick disconnect fittings on the hose to be securely latched. The hoses can appear to be connected but are not in fact locked together. Hoses left in such a condition can fall apart at any time. To address this possibility, all laboratory analysts have been instructed to ensure quick disconnects are securely fastened before leaving the CAM.

* Previous Similar Events:

BFRO-50-296/82008, 82040
50-259/82060

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: J.R.R.