

LICENSEE EVENT REPORT

CONTROL BLOCK: [1 2 3 4 5 6] 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 01 | M I D C C | 1 | 0001-00000000-000 | 3 | 411111 | 4 | [] | 5

7 8 9 14 15 25 26 30 37 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 5 | 7 | 1 | 1 | 1 | 8 | 8 | 2 | 8 | 1 | 2 | 0 | 8 | 8 | 2 | 9

60 61 68 69 74 75 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | DURING NORMAL OPERATION, THE FIRE DETECTION SYSTEM ALARM FOR ZONE 2 IN THE AUX BUILD-

03 | ING WAS RECEIVED IN THE CONTROL ROOM. INVESTIGATION FOUND A PYRALARM DETECTOR ALARM-

04 | ING FOR NO APPARENT REASON. A FIRE WATCH WAS ESTABLISHED IN THE AREA OF THE ALARMING

05 | DETECTOR UNTIL THE SITUATION WAS CORRECTED. THIS CONDITION REMOVED ANY FURTHER CAP-

06 | ABILITY FOR THE FIRE DETECTION SYSTEM TO ALARM IN THE CONTROL ROOM IF ANY ADDITIONAL

07 | PYRALARMS WITHIN THIS ZONE ALARMED. THIS DESIGN FEATURE WAS EXPLAINED IN DETAIL IN

08 | RO-050/315-096. THIS EVENT WAS NON-CONSERVATIVE WITH RESPECT TO TECH. SPEC. 3.3.3.7.

8 9

09 |

SYSTEM CODE [A B] 11 CAUSE CODE [E] 12 CAUSE SUBCODE [E] 13 COMPONENT CODE [I N S T R U] 14 COMP. SUBCODE [E] 15 VALVE SUBCODE [Z] 16

9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 8 | 2 | | | | | | | | | | | | | | | |

21 22 23 24 26 27 28 29 30 31

EVENT YEAR OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN [E] 18 FUTURE ACTION [Z] 19 EFFECT ON PLANT [Z] 20 SHUTDOWN METHOD [Z] 21 HOURS [0 | 0 | 0 | 0] 22 ATTACHMENT SUBMITTED [N] 23 NFRD-4 FORM SUB. [Y] 24 PRIME COMP. SUPPLIER [A] 25 COMPONENT MANUFACTURER [P | 4 | 3 | 5] 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | INVESTIGATION FOUND THAT THE ALARM SETPOINT ON THE PYRALARM DETECTOR WAS LOW. THE

11 | DETECTOR ASSEMBLY WAS CLEANED AND THE ALARM SETPOINT WAS ADJUSTED TO THE PROPER VALUE.

12 | THE DETECTOR WAS VERIFIED TO BE OPERATING CORRECTLY AND THE SYSTEM WAS RETURNED TO

13 | SERVICE. FURTHER ACTION TO MINIMIZE DETECTOR INOPERABILITY TIME IS EXPLAINED IN

14 | RO-050/315-096.

8 9

FACILITY STATUS [E] 28 % POWER [1 | 1 | 0 | 0] 29 OTHER STATUS [NA] 30 METHOD OF DISCOVERY [B] 31 DISCOVERY DESCRIPTION [OPERATOR OBSERVATION] 32

8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE [Z] 33 [Z] 34 AMOUNT OF ACTIVITY [NA] 35 LOCATION OF RELEASE [NA] 36

8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER [0] 37 TYPE [Z] 38 DESCRIPTION [NA] 39

8 9 11 12 13 80

PERSONNEL INJURIES NUMBER [0] 40 DESCRIPTION [NA] 41

8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE [Z] 42 DESCRIPTION [NA] 43

8 9 10 80

PUBLICITY ISSUED DESCRIPTION [N] 44

8 9 10 80

8212170292 821208
PDR ADOCK 05000315
PDR

NRC USE ONLY

NAME OF PREPARER R. A. PALMER

PHONE 616-465-5901

GPO 91-026