

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I I D C C | 1 2 | 0 0 - 0 0 0 0 0 - 0 0 | 3 4 | 1 1 1 1 | 4 5
7 8 9 | LICENSEE CODE 14 15 | LICENSE NUMBER 25 26 | LICENSE TYPE 30 37 CAT 38 58

CON'T
0 1 | REPORT SOURCE | L 6 | 0 5 0 0 0 3 1 5 | 7 1 | 1 2 7 8 2 | 3 1 | 2 0 8 8 2 | 9
7 8 9 | DOCKET NUMBER 58 59 | EVENT DATE 74 75 | REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | DURING NORMAL OPERATION, FIRE DOOR #387, AT THE ENTRANCE TO QUADRANT #2 OF THE AUX.
0 3 | BLDG. AROUND UNIT 1 CONTAINMENT, WAS FOUND IN A CONFIGURATION THAT WAS NONCONSERVA-
0 4 | TIVE IN RESPECT TO T.S. 3.7.10. THE ACTIVE LEAF OF THE DOUBLE DOORS WAS CLOSED
0 5 | BEFORE THE INACTIVE LEAF, PREVENTING THE INACTIVE LEAF FROM CLOSING COMPLETELY. THE
0 6 | ACTION REQUIREMENTS WERE MET BY RETURNING THE DOORS TO THE PROPER CONFIGURATION.
0 7 | PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. THIS WAS THE FIRST OCCURRENCE OF THIS
0 8 | TYPE.

0 9 | SYSTEM CODE | X X 11 | CAUSE CODE | A 12 | CAUSE SUBCODE | X 13 | COMPONENT CODE | X X X X X X 14 | COMP SUBCODE | Z 15 | VALVE SUBCODE | Z 16
7 8 9 | 10 11 12 13 14 15 16
17 | LER RC REPORT NUMBER | 8 2 | EVENT YEAR | 21 22 | SEQUENTIAL REPORT NO. | 1 0 3 | OCCURRENCE CODE | 1 0 3 | REPORT TYPE | L | REVISION NO. | 0
23 24 25 26 27 28 29 30 31
18 | ACTION TAKEN | Z 18 | FUTURE ACTION | Z 19 | EFFECT ON PLANT | Z 20 | SHUTDOWN METHOD | Z 21 | HOURS | 0 0 0 | ATTACHMENT SUBMITTED | N 23 | NPRO-4 FORM SUB. | N 24 | PRIME COMP. SUPPLIER | A 25 | COMPONENT MANUFACTURER | Z 9 9 9 9 26
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | AN INSPECTION OF THE FIRE DOOR DETERMINED THAT ALL OF THE DOOR HARDWARE FUNCTIONED
1 1 | PROPERLY. SINCE THE INACTIVE LEAF IS EQUIPPED WITH FLUSH BOLTS AND THE DOUBLE DOORS
1 2 | ARE EQUIPPED WITH A COORDINATOR WHICH MUST BE MANUALLY OVERRIDEN TO CLOSE THE ACTIVE
1 3 | LEAF FIRST, THE DOOR HAD TO BE PLACED IN THIS CONDITION INTENTIONALLY. THE RESPON-
1 4 | SIBLE INDIVIDUAL COULD NOT BE DETERMINED.

1 5 | FACILITY STATUS | E 28 | % POWER | 1 0 0 | OTHER STATUS | NA 30 | METHOD OF DISCOVERY | A 31 | DISCOVERY DESCRIPTION | OBSERVATION DURING PLANT TOUR 32
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z 33 | Z 34 | AMOUNT OF ACTIVITY | NA 35 | LOCATION OF RELEASE | NA 36
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1 7 | PERSONNEL EXPOSURES NUMBER | 0 0 0 | TYPE | Z 38 | DESCRIPTION | NA 39
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1 8 | PERSONNEL INJURIES NUMBER | 0 0 0 | DESCRIPTION | NA 41
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z 42 | DESCRIPTION | NA 43
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
2 0 | PUBLICITY ISSUED DESCRIPTION | N 44 | NA 45
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

8212170296 821208
PDR ADOCK 05000315
S PDR

NRC USE ONLY

NAME OF PREPARER D. G. WIZNER

PHONE 616-465-5901