(704)875-4000

Duke Power Company McGuire Nuclear Station 12700 Hagers Ferry Road Huntersville, NC 28078-8985



\* 1

# DUKE POWER

February 28, 1991

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: McGuire Nuclear Station Unit 1 Docket No. 50-369 Licensee Event Report 369/90-23-01

## Gentlemen:

Pursuant to 15 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 369/90-23-01 transmitting additional information as committed in LER 369/90-23 dated September 20, 1990. This report is being submitted in accordance with 10 CFR 50.73(a)(2)(i). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

1 my 2. M. Comel

T.L. McConnell

DVE/ADJ/cb1

Attachment

103060148 DR ADOCK

xc: Mr. S.D. Ebneter Administrator, Region II U.S. Nuclear Regulatory Commission 101 Marietta St., NW, Suite 2900 Atlanta, GA 30323

> INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

M&M Nuclear Consultants 1221 Avenue of the Americas New York, NY 10020 Mr. Tim Reed U.S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555

Mr. P.K. Van Doorn NRC Resident Inspector McGuire Nuclear Station

(RC Form 364 9-8-1		LICE	INSE	E EVEN	T REP	ORT (	LER)	U.S. NU	CLEAR RE APPROVED EXPIRES 1	GULATOR DOMBINO 131.68	Y COMMI 3160-010	5510N 4
ACILITY NAME IT								DOCKET NUMBER	(2)	- T	PAST	-51
McGuire	Nuclear Sta	tion,	Unit	1				0 15 10 10	10131	0 1 9	1 [OF]	16
Both Trains	Of The Cont	rol Ro	om Ve	entila	tion !	System	n Were Ir	operable	Becau	se Of		
An Equipment	LER NUMBER (8	Tunct	100 AFF	ORT DATE	1		OTHER	FACILITIES INVO	LVED (8)			
WONTH DAY YEAR YEAR	SEQUENTIAL	RE VESCA	MONTH	0.4 Y	Y E.A.F.	N.O	facilite na	des .	DOCKET	NUMBER	-	2 0
						MCGI	lire Unit		0 [5]	0101	013	10
0 8 2 1 9 0 9 0	- 0 2 3 -	- 0 1	0 9	2 0	9 0				0   5	0 1 0 1	011	1
OFERATING 1 THIS RE	PORT IS SUBMITTED	PURSUANT T	O THE RI	COUNTEMEN	ITS OF 10	CFR & IC	hard one or more	ar the follow right in	1 23	51.(b)		
20 million and a million of the	402(6)		50 38(-1	en e			50 73(a)(2)(v)		73	75 (e)		
LOVEL 1 0 0 20	406(a)(3)(n)	Sec. Com	80.3812	1(2)		-	50 73(s1(2)(m))		01	HER (Sale)	A. 12 401	tracit Kourr
and concernation of the second second second 20	405(a)(1)(iii)	X	60 73(#	(42)(7)			60 73(x)(2)(v(ii)	A)	181	LA.		
20	405 (# 213 ) () «?		80 73ix	1021100			60 7.3(x)(2)(vu())		1.10			
20	406 (a) (1) (v)		50.734	121(01)	0.0.0		60.73(a)(2)(x)		L			
VAME			CENSEL	CONTACT	UR THIS	(em (52)			TELEPHO	NE NUMB	E PI	
		1.5.5						AREA CODE				
Alan Sipe, Chairma	n, McGuire	Safety	Revi	lew Gr	oup	1		1704	8 7	2 1	4 1	81
n per sense i den de se sensione, de seus e seus e sension de seus e se traverse e sension Nota esta en la seus e persona de sension de generation de seus estas de la seus estas de seus estas de seus es	COMPLETE OF	NE LINE FOR	EACH CO	OMPONENT	FAILURE	DESCRIBE	D IN THIS REPO	RT (13)				
CAUSE SYSTEM COMPONENT	MANUFAC TURER	EPORTABLE TO NPRDS			SAUSE	SYSTEM	COMPONENT	MANUFAC YURER	REPOR TO N	PROS	at the spin of the other	
1 1 1 1	1.1.1.					1		1.1.1				
					1.1	14	1.51	D. C. F				
	SUPPLEMEN	TAL REPORT	EXPECTI	ED (14)	********	have been a	un nitra sideranden	EXPERIM	180	MONTH	DAY	YEAP
								SUBMISS DATE	10N 161			
YES (11 ver complete EXPECTED	SUBMISSION DATE:		2	X NO				and the second		hanna hanna	-	hunde
On August 20 System was d Mechanical M Air Handling modification check reveal sheared off. 1705. At th TS 3.0.3 was was declared Train A VC s Units 1 and time of this Failure/Malf an analysis Design Engin solutions to	9, 1990, at leclared ind laintenance (Unit (AHU) of that the ed that the The Train lat time, bo entered. I operable of system and 2 were in N event. The function. I of the fail heering (DE o this problem)	0230, operabl (MNT) ) at ap rain. e Train n A VC oth tra Work o on Augu it was Mode 1 his eve Product led par ) perso lem.	Train e for perso proxi Train A V( AHU w ins c n Tra st 21 decla (Powe nt is ion § ts tc nnel	n B of r modi onnel imatel n A VC C AHU was su of the ain B 1, 199 ared o er Ope s assi Suppor o dete will	the ficat condu y 163 was motor bsequ VC sy 0, at perab ratio gned t Dep rmine evalu	Contro ion an oted a o, in base ently ystem 1755 le on n) at a cau artme the ate t	ol Room M nd funct a check of preparat rvice at tension declared were ind was comp. Repai August A 100 per se of Eq nt (PSD) cause of his fail	Ventilati ional tes of the Tr tion for this tim ing bolts d inopera perable leted and rs were m 22, 1990, cent powe uipment personne the fail ure and r	on (V( ting. ain A e. Th were ble at and the to at 18 r at 18 r at 19 l cond ure.	VC VC train train o the 345. the ducte	đ	

NRC Form 386 (9.83)

\$ .

14

U.S. NUCLEAR REQULATORY COMMISSION

APPROVED OMB NO 3150-0104 EXPIRES 8/31/48

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
McGuire Nuclear Station, Unit 1	0 2 0 0 0 3 6 9	9 0 - 0 2 3 - 0 1	2 OF 16

#### EVALUATION:

RC Form 366A

## Background

There are two independent trains of the Control Area Ventilation [EIIS:VI] system which are designed to maintain a habitable environment in the Control Room [EIIS:NA], Control Room Area, and Switchgear [EIIS:SWGR] Rooms during normal and accident conditions. Based on these criteria, the system is designed as an Engineered Safeguards Features [EIIS:JE] system with absolute and carbon filtration [EIIS:FLT] in the outside air intakes and with equipment redundancies for use as conditions require. The Control Room is designed to be maintained at a positive pressure of >/= 0.125 inches water gauge (w.g.), relative to outside atmosphere during an accident to prevent entry of contaminants. Two 100 percent capacity Outside Air Pressure Filter Trains pressurize the Control Room by providing approximately 1000 cubic feet per minute (cfm) of filtered outside air in addition to approximately 1000 cfm of filtered recirculated Control Room air.

Technical Specification (TS) 3/4.7.6 includes requirements that in Mode 1 (Power Operation), Mode 2 (Startup), Mode 3 (Hot Standby), and Mode 4 (Hot Shutdown), with one train of the VC system inoperable, the inoperable train must be restored to operable status within seven days or be in at least Hot Standby within the next six hours, and in Mode 5 (Cold Shutdown) within the next thirty hours. With both trains of VC inoperable and the unit in Mode 1, the specified action is to comply with TS 3.0.3. TS 3.0.3 requires that within 1 hour action must be initiated to place the unit in a mode in which the TS does not apply. TS 3.7.6 applies to Unit 1 and Unit 2 because the VC system is shared by both units.

#### Description of Event

On August 20, 1990, at 0230, the Train B VC system was declared inoperable for implementation of Nuclear Station Modification MG-53370, Revision 0.

On August 21, 1990, at approximately 1630, MNT personnel performed a check of the Train A VC AHU [EIIS:AHU], while preparing to implement the same modification on that train. The Train A VC system, which was inservice at the time, was found to be damaged. The tensioning bolts on the Train A VC AHU motor [EIIS:MO] base plate were sheared off.

MNT personnel then informed the Shift Supervisor (SS) of the damage to the Train A VC AHU. Work Request 141514 was written to repair the damage to the Train A VC AHU motor base plate tensioning bolts. The SS contacted the Maintenance Engineering Services (MES) personnel responsible for ventilation systems. Upon examination of the damaged component, the Train A VC system was declared inoperable at 1705 and TS 3.0.3 was entered. Initial examination of the damaged parts indicated that the probable cause of this failure was fatigue.

US NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-C104 EXPIRES 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)	
		YEAR SEQUENTIAL REUSION NUMBER NUMBER	
McGuire Nuclear Station, Unit 1	0 15 10 10 10 13 1 6 9	9 0 - 0 2 3 - 0 1 3 0F	16

The work on the Train B VC system was subsequently completed and Train B was declared operable on August 21, 1990, at 1755 and TS 3.0.3 was exited.

Repairs were started on the Train A VC AHU. MNT personnel contacted the onsite Design Engineering (DE) staff to determine what type/grade of materials to use. DE personnel determined that the tensioning bolts and base plate material type were not specified on the manufacturers drawings. A McGuire Exempt Variation Notice (MEVN 2444) was originated to fabricate the new bracket to the criginal design, using A+36 type carbor steel.

While these repairs were being completed, an additional problem was discovered regarding the Train A VC AHU. Inleakage was identified on the AHU housing. This event is addressed in LER 369/90-24, which is presently under investigation.

Repair of the Train A VC AHU, including the sealing of inleakage, was completed on August 22, 1990. The Train A VC system was decla d operable at 1845.

DE personnel are evaluating the failure of the tensioning bolts, applicability of this problem to the Train B VC AHU, and applicability to other ventilation systems. Analysis of the failed parts by PSD personnel was requested by DE.

## Conclusion

Form 366A

This event has been assigned a cause of Equipment Failure/Malfunction. The tensioning bolts were damaged such that the only tension being maintained on the Irain A VC AHU belts was the weight of the motor itself.

Discussions with MES and DE personnel indicate that the Train A VC AHU has previously experienced higher vibration than exhibited by the Train B VC AHU. Pending the results of the analysis of the failed parts, it appears that the tensioning bolts may have failed due to fatigue caused by vibration. It has been determined that this problem does not represent an operability concern on the other redundant train because of the lower vibration levels experienced by Train B VC AHU. MEVN 2359, completed August 9, 1990, addressed the vibration problem on Train A VC AHU. Although the Train A VC AHU motor continues to exhibit some high vibration, initial feedback on the effectiveness of this modification indicates that vibration levels have been considerably reduced.

During the repair of the Train A VC AHU, DE personnel discovered that the manufacturer's drawings did not specify the material type used in the motor base plate/tensioning bolt assembly. Per MEVN 2444, MNT personnel used type A-36 materials. The materials used were also of a larger physical size (i.e. larger diameter).

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
McGuire Nuclear Station, Unit 1	0   5   0   0   0   3   6   9	9 0 - 0 2 3 - 0 1	4 OF 16
TEXT (If more space is required, use editribunal NRC Form 366.6 2) (17)			

This failure is believed to have been caused by a vibration problem unique to the Train A VC AHU, and the motor base plate design used on the VC system, which is not commonly used on other ventilation systems.

DE personnel will evaluate this failure and make recommendations as to the best possible solution to this problem.

A review of the Operating Experience Program data base for the past twenty-four months prior to this event revealed one event involving TS violations because of Equipment Failure/Malfunction of the VC system. This problem was documented in LER 369/89-18. Both trains of the VC system were made inoperable when a Nuclear Service (RN) [EIIS:BI] system valve [EIIS:FCV], 1RN-460, Control Room Air Conditioning Condenser B Control No. 2, failed to open. Since both trains of the VC system were made inoperable due to an equipment failure, the problem is considered to be recurring. Corrective actions for LER 369/89-18 would not have prevented this problem from occurring.

This event is not Nuclear Plant Reliability Data System (NPRDS) reportable.

There were no personnel injuries, radiation overexposures, or uncontrolled releases of radioactive material as a result of this event.

CORRECTIVE ACTIONS:

Immediate: Actions were taken to restore the Train 'B' VC system to an operable status.

Subsequent:

ERC Form 386A

- Train A VC system was repaired under Work Request No. 141514.
  - 2) DE personnel evaluated the applicability of this failure to the Train B VC system and other ventilation systems and determined that this failure was not applicable to those systems due to their lower vibration levels.
  - 3 PSD personnel analyzed the failed parts to determine the failure mode.

Planned:

- DE personnel will evaluate this failure and make recommendations as to the best possible solution to this problem.
- McGuire Safety Review Group (MSRG) personnel will submit an addendum to this report upon completion of the DE evaluation.

U.S. NUCLEAR REQULATORY COMMISSION

#### APPROVED OME NO. 3150-0104 EXPRANE P 31188

FACILITY NAME 1.	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL NEVISION NUMBER NUMBER	
McGuire Nuclear Station, Unit 1	0 15 10 10 10 13 1 6 9	9 0 0 2 3 0 1	5 OF 16

## SAFETY ANALYSIS:

RC Form 366A

The design requirements of the VC system are to supply filtered air at a controlled temperature and humidity and to pressurize the Control Room to 0.125 inches w.g. A positive pressure of 0.05 inches w.g. is considered sufficient to prevent inleakage in excess of 10 cfm, which is the assumed leakage value used for radiation dose calculations in Chapter 15 of the Final Safety Analysis Report (FSAR).

Failure of the tensioning assembly could very likely have resulted in the belt jumping off the AHU or motor pulley. This would have resulted in a loss of air flow in that train. With the other train inoperable, Control Room temperature would rapidly increase and exceed the TS limit of 90 degrees F.

Normal Control Room temperature is 75 degrees F. The Control Room temperature is verified to be </= 90 degrees F once every 12 hours per procedure PT/A/4600/03A, Semi-Daily Surveillance Items. Loss of both trains of VC would likely result in the Control Room temperature exceeding 90 degrees F in less than the 12 hour surveillance cycle. Operators would notice such an increase. The operators would also receive alarms indicating problems with the VC system. Operator response to an increasing control room temperature would include implementation of procedure AP/0/A/5500/38, Control Room Hi Temperature, which specifies actions to be taken to mitigate the consequences of a high control room temperature. Operator action under TS 3.0.3 would commence as soon as both trains of the VC system were determined to be inoperable. Sufficient time would exist to bring the units down to Mode 3 and subsequently, Mode 5 (Cold Shutdown).

Although the Train A VC AHU was declared inoperable due to the sheared tensioning bolts, this AHU continued in service during the 50 minute interval until Train B VC system was returned to operability. During this time, Train A VC AHU continued to provide air flow to the Control Room.

During this event, there were no accidents that would have required operation of the VC system to maintain habitability of the Control Room.

The principle contaminant contained in air leaking into the Control Room is assumed to be radioactive Iodine. Very low amounts of Iodine would be expected to reach the area around the Control Room since this requires passage through either Auxiliary or Turbine Building Ventilation systems [EIIS:VF,VK] or passageways first.

Control Room Operator dose well be further reduced by operation of the Auxiliary Building Ventil (1) system. No credit is taken for the VA filtration, with regard to (1) Room dose calculation, in mitigating the Emergency Core Cooling System (2) kage source. However, this system is automatically switched to the filtered exhaust mode of operation on an accident or Blackout signal or if radiation is detected by the exhaust monitor [EIIS:MON]. The VA system has two trains (Unit 1 and Unit 2) which respond to an accident on either unit thus providing essentially redundant

LICENSEE	EVENT REPORT	(LER) TEXT	CONTINUATION
----------	--------------	------------	--------------

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OM8 NO. 3150-0104 EXPIRES 8/31/86

	and the second	And the second	A REAL PROPERTY OF A REAL PROPER
FACILITY NAME (1)	DOCKET HUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
McGuire Nuclear Station, Unit 1	0 15 10 10 10 13 1 6 9	9 0 - 0 2 3 - 0 1	160F 16
TEXT IN more spans a memored use excitioned NRC Form 3984 1/117	denor distant in the second		

protection. Operation of the VA system in the filtered exhaust mode by either train of the system would serve to reduce the calculated dose to Control Room personnel.

In the event the Control Room atmosphere became unbreathable, self contained breathing apparatus (SCBA) provided in the Control Room area could be employed. Radiation monitors in the Control Room would alert Control Room personnel of high radiation levels.

The health and safety of the public were not affected by this event.

# ADDITIONAL INFORMATION:

IRC Form 306A

Evaluation of this failure by DE personnel resulted in two additional corrective actions to resolve the problem.

The first corrective action requires the redesign of the Train A VC AHU motor base plate to use a slide rail type arrangement. The second corrective action involves the replacement of the existing drive belt on the Train A VC AHU with a Browning or Gates model 112 belt. The combination of these corrective actions will enhance the capability to align the motor to its proper position.