

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | T | P | S | 3 | 2 | 00 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

01 | L | 9 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 0 | 7 | 1 | 2 | 0 | 1 | 8 | 2 | 3 | 1 | 2 | 1 | 5 | 8 | 2 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal full power operation, the 3A load center was de-energized

03 | following a trip of the associated 4kV breaker, 3AA08. This resulted in the

04 | loss of the 3A motor control center, which is reportable under T.S.6.9.2.a.2)

05 | The breaker was closed five minutes later and power was restored. The

06 | breaker has remained closed since the incident and no other problems have

07 | occurred. The health and safety of the public were not affected. A

08 | similar event was reported as LER-251-82-001.

09 | E | B | 11 | X | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 | LER/R0 REPORT NUMBER | 8 | 2 | 21 | 22 | - | 23 | 0 | 1 | 8 | 24 | 26 | / | 27 | 0 | 1 | 28 | 29 | T | 30 | - | 31 | 0 | 32

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 | X | 19 | X | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | N | 24 | Y | 25 | Z | 26 | Z | 27 | 9 | 28 | 9 | 29 | 9 | 30

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRM FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The root cause could not be determined. An inspection of the breaker and

11 | circuitry found no apparent signs of equipment malfunction. During the

12 | next outage of sufficient duration, the breaker's protective relays will be

13 | tested for proper operation to verify that equipment malfunction did not

14 | play a part in this event.

15 | E | 18 | 1 | 0 | 0 | 29 | NA | 30 | A | 31 | Operational Event | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL INJURIES NUMBER DESCRIPTION

19 | Z | 42 | NA | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 | N | 44 | NA | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER: Z. E. Berry PHONE: (305) 245-2910, Ext. 353

8212210207 821215
PDR ADOCK 05000250
S PDR