U. S. NUCLEAR REGULATORY COMMISSION

(7-77)		LICENSEE EVENT REPORT	Attachment to AECM-82/631 Page 1 of 1
	CONTROL BLOCK:	(PLEASE PRINT OR TYPE	ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0	- 0 0 0 0 - 0 0 3 26	LICENSE TYPE 30 4 57 CAT 58 5
0 1 7 8	REPORT L 6 0 5 10 0 SOURCE 60 61 DOCK	0 4 1 6 7 1 1 2 7 8 2 ET NUMBER 68 69 EVENT DATE CONSEQUENCES (10)	8 1 2 2 2 8 2 9 74 75 REPORT DATE 80
0 2		Meteorological Monitoring System	was removed from service
0 3	for approximately 7.5 hour	rs to perform work as required by	design change package
0 4	82-457. An LCO was enter	ed in accordance with T.S.3.3.7.3.	. This had no effect on
0 5	the health and safety of	the public and did not constitute	a threat to plant safety.
0 6	The event is being report	ed pursuant to T.S.6.9.1.13.b.	
0 7			
0 8	9		8G
[0]	SYSTEM CAUSE CODE CODE	CAUSE SUBCODE COMPONENT CODE	SUBCODE SUBCODE
7 8	9 10 11	12 13 18 OCCURRENCE	19 20 REPORT REVISION
	17) REPORT EVENT YEAR	REPORT NO. 1 4 5 0 3	TYPE O O
		THOO HOURS (22) SUBMITTED FORM 2 (21) 0 0 0 0 N (23) 1	RD-4 PRIME COMP. COMPONENT MANUFACTURER V 24 Z 25 Z 9 9 1 9 2 47
10	The event was caused by a	planned maintenance outage. DCP	82-457 was implemented to
	change breakers and circu	it wires to meet NRC requirements.	. The system was restored
1 2	on November 27, at 1530 h	ours and the LCO was lifted. This	s is submitted as a final
[1]3	report.	أساد المستميل مستواني مسول	
1 4			
16	PACILITY SPOWER OT B 28 0 0 0 0 29 NA	HER STATUS 30 METHOD OF DISCOVERY A 31 Planned	DISCOVERY DESCRIPTION (32) Activity
	Z (33) Z (34) NA	DF ACTIVITY (35) NA	LOCATION OF RELEASE (36)
	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 0 0 0 37 Z 38 NA	44 45	80
7 8	9 PEPSUN PL NUURIES NUMBER DESCRIPTION (41) NA		80
7 8	9 11 12 OSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION	8212300200 821222 PDR ADDCK 05000416	80
1 9	Z (42) NA	SPDR	80
20	ISCUES DESCRIPTION 45 NA		NRC USE ONLY
		inal Signed by Ron Byrd	HONE