LICENSEE EVENT REPORT UPDATE REPORT - PREVIOUS

*	REPORT DATE 2/19/80 CONTROL BLOCK:
0 1	G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 2 1 7 0 1 2 7 8 0 8 1 2 1 6 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  [During normal steady state power operation, the "A" Reactor Recirculation
0 3	Pump tripped causing a reactor power reduction from 2425 MWt to 1103 MWt.
0 4	Unit operation continued for 23 hours using the "B" Reactor Recirculation
0 5	Pump per Tech. Specs. 3.6.J.2. This is not a repetitive event. There
0 6	were no effects on public health or safety due to this event.
0 7	lies in extens on passive hearter of safety and to this event.
Name of Street	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
10	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
11	penetration. The short circuit was the result of corrosion on a terminal J
1 2	board caused by moisture condensation from a steam leak in the drywell.
13	The steam leak was repaired. The terminal board was replaced and tested
14	satisfactorily. The pump was returned to normal operation.
1 5	PACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA A 44 45 46 OPERATOR ODSERVATION 30 NO NA
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  NA NA LOCATION OF RELEASE (36)  PERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35)  NA N
7 8	O O O O O O O NA  PERSONNEL INJURIES  NA  80
1 3	0 10 10 10 DESCRIPTION (41) NA NA
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA  9 10 8212300270 80404
20	NA PDR
	NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851