

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 P A S E S I 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 13 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 8 7 7 1 2 1 3 8 2 8 0 1 1 2 8 3 9  
7 8 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the Startup Testing Program, the "B" control structure chlorine detector

03 was inoperable due to a non-functioning drip leg. This is determined reportable

04 per 6.9.1.9.b. There were no adverse consequences in that the redundant

05 detector was operable and no chlorine spill occurred.

06

07

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
S G 11 B 12 A 13 Z Z Z Z Z Z 14 Z 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER/RO REPORT NUMBER 8 2

18 ACTION TAKEN X

19 FUTURE ACTION F

20 EFFECT ON PLANT Z

21 SHUTDOWN METHOD Z

22 HOURS 0 0 0 0

23 ATTACHMENT SUBMITTED Y

24 NPRO-4 FORM SUB. N

25 PRIME COMP. SUPPLIER Z

26 COMPONENT MANUFACTURER Z 9 9 9

27 SEQUENTIAL REPORT NO. 0 7 3

28 OCCURRENCE CODE 0 3

29 REPORT TYPE L

30 REVISION NO. 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The drip leg had dried out due to continuous operation of the heat tracing on

11 the sample line. The sensor controlling the heat trace monitored outside air,

12 therefore, low outside air temperature activated the heat trace. However, when

13 the sample line temperature increased, the sensor did not self-correct and

14 shut-off. (continued)

15 FACILITY STATUS B 28 % POWER 0 4 5 29 n/a OTHER STATUS 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32 operator observation

13 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY 35 n/a LOCATION OF RELEASE 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION 39 n/a

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION 41 n/a

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43 n/a

20 PUBLICITY ISSUED DESCRIPTION 44 n/a

NRC USE ONLY

NAME OF PREPARER D.G. Mitchell

PHONE: (717) 542-2181 X524

Attachment

Licensee Event Report 82-073/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Item #27 continued):

A temporary modification has moved the sensor to the sample line, and the necessary paperwork will be initiated to make this change a permanent modification.