



Carolina Power & Light Company

Brunswick Nuclear Project  
P. O. Box 10429  
Southport, N.C. 28461-0429

March 19, 1991

FILE: B09-13510C  
SERIAL: BSEP/91-0121

10CFR50.73


U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2  
DOCKET NO. 50-324  
LICENSE NO. DPR-62  
SUPPLEMENT TO LICENSEE EVENT REPORT 2-90-008

Gentlemen:

In accordance with Title 10 of the Code of Federal Regulations, the enclosed Supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and was submitted in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,



J. W. Spencer, General Manager  
Brunswick Nuclear Project

TMJ/

Enclosure

cc: Mr. S. D. Ebnetter  
Mr. N. B. Le  
BSEP NRC Resident Office

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Brunswick Steam Electric Plant Unit 2

DOCKET NUMBER (2)

05000324

PAGE (3)

01 OF 10

TITLE (4) SCRAM Resulting from Turbine Trip on High Level due to Blown Fuse in FW Logic

EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQ. NO.	REV. NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
08	16	90	90	- 008	- 02	03	19	91			

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

OPERATING MODE (9)	1	20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10)	100	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vi)	OTHER (Specify in Abstract and Text)
		20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(vii)(A)	
		20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(vii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(x)	

## LICENSEE CONTACT FOR THIS LER (12)

NAME THERESA M. JONES, REGULATORY COMPLIANCE SPECIALIST

TELEPHONE NUMBER

(919)- 457-2039

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS
X	SB	--FU	S156	Y					

## SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
	X					

## ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (16)

On August 16, 1990, Unit 2 reactor was at 100% power. The RPS, HPCI, RCIC, ADS, RHR/LPCI, CS, SBT, SLC, DG and plant electrical system were operable in standby readiness. The reactor level control system was operating in automatic - three element control and at 165 inches. At 0942, the reactor automatically shutdown on a "TSV Fast Closure" RPS trip signal caused by a turbine trip on reactor high water level. During this event, the HPCI turbine stop valve cycled closed and then open, water intrusion into the HPCI oil was noted, the RCIC barometric condenser vacuum pump experienced an electrical fault, and a loss of the recirculation pumps resulted in temperature transients in the vessel. HPCI and RCIC operability were not affected; the recirculation pumps are now being powered from the start up auxiliary transformer to prevent their loss during future reactor trips. The cause of this event was failure of primary power fuse C32-F5, which supplied power to the steam flow inputs of the three element feedwater control logic. Loss of the steam flow inputs resulted in a maximum demand signal to the RFPs and a rapid increase in reactor level up to the high level turbine trip point which, in turn, caused a reactor scram on TSV position. Primary power fuse C32-F5 and its associated circuit were evaluated. The fuse has been replaced. The final Harris Energy and Environmental Center (HE&EC) report concluded that the fuse did not exhibit defects which could be interpreted as the cause for the fuse failure. The cause for the fuse failure is indeterminate. The HE&EC is continuing an analysis of the Gould Shawmut fuses. Past similar events include LERs 2-88-018, 1-88-023 and 2-90-008. The safety significance of this event is minimal. The plant responded as designed.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)
Brunswick Steam Electric Plant Unit 2	05000324	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER
		90	-	008	-	02
						02 OF 10

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

INITIAL CONDITIONS

On August 16, 1990, Unit 2 reactor was at 100% power. The RPS, HPCI, RCIC, ADS, RHR/LPCI, CS, SBT, SLC, DG and plant electrical system were operable and in standby readiness. The reactor feedwater level control system was operating in automatic - three element control and level was being maintained at 185 inches (ie; normal operating level). Reactor pressure was 1002 psig.

EVENT DESCRIPTION

At 0942 on August 16, 1990, the Unit 2 reactor automatically shutdown on a "TSV Fast Closure" RPS trip signal. The TSV fast closure was caused by a turbine trip on reactor high water level. Preceding the reactor trip, the RO observed the four individual steam flow indications (2-C32-R603A through D) rapidly decrease to zero. A loss of the total steam flow indication on the steam flow/feed flow recorder (2-C32-FR-R607) was also noted. The RO responded to the resulting level transient by adjusting the feedwater master control level setpoint. When the transient continued, the RO placed the feedwater master control system to manual. At that time, the RO noted an erratic increase in reactor level which subsequently increased to the high water level turbine trip setpoint (208 inches). The turbine tripped off line and the reactor scrambled on TSV Fast Closure. After the scram, the RO performed automatic actions required by the EOPs and subsequent actions were directed by the SF utilizing the EOP flowchart Path-3, High Power SCRAM. The RFPs had also tripped on the high level. The corresponding loss of feed flow to the reactor resulted in level decreasing. At 166 inches a LL#1 signal was generated and PCIS groups 2 and 6 automatically isolated. Group 8 also received an isolation signal but the valves were already closed and automatic actuation did not occur, per design. At 0946, to increase reactor level, RCIC was manually initiated at 135 inches reactor level. At 0948, HPCI was manually initiated at 122 inches. At 0949, a second RO started the 2A RFP and began injecting feedwater into the vessel. With reactor level restored and pressure stabilized, the EOP was exited and GP-05, Unit Shutdown, was entered at 0955.

EVENT INVESTIGATIONSEQUENCE OF EVENTS/INVESTIGATION

09:41:56 A primary power fuse (C32-F5) fails open in the Feedwater Level Control System (FWLCS), panel (H12-P612). Power is lost to modules C32-4405A/D, K616, K620, K628 and K650. Power loss to C32-4405A/D causes an immediate loss of the four steam flow signals.

Loss of primary power to power supply C32-K620 causes loss of indication of Turbine Steam (First stage pressure) and narrow range reactor pressure. These signals drop to zero about 2 seconds after the loss of power. This delay is consistent with capacitors in the power supply.

Loss of power to trip module C32-K628 will supply a partial permissive for the 45% speed reactor recirculation pump runback circuit, however due to later events, this runback does not play a part in the event.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)

Brunswick Steam Electric Plant Unit 2

DOCKET  
NUMBER (2)

05000324

LER NUMBER (6)

PAGE (3)

YEAR

90

-

SEQUENTIAL  
NUMBER

008

REVISION  
NUMBER

02

03 OF 10

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

The most serious problem is created by loss of power to modules K616 and K650. Because FWLCS is operating in "3 Element", the power loss causes the level feedback signal going to the master feedwater controller (R600) to drop to zero. The controller "sees" this as a low reactor level and increases the speed demand signal to both the "A" and "B" feedpump turbines. The pumps speed up; level in the vessel begins to climb.

Note: It is possible the output of module C32-K650 would vary erratically during the time DC power inside the module is decaying away. This in turn could cause the deviation meter on the master controller to swing and give the appearance of erratic level swings.

The cause of the Gould Shawmut A25Z2 fuse (ie; C32-F5) failure has not been determined. The circuit was investigated by I&C personnel and no abnormal loading was found. The fuse was replaced. The original fuse is an Appendix R fuse which places its installation at three to five years ago but a definite date has not been determined. The failed fuse was sent to the Harris Energy and Environmental Center (HE&EC) for failure analysis. As a precautionary measure, the unit was returned to operation in single element control to prevent a loss of feedwater control should the fuse fail again. The fuse performance was reviewed by the Plant Nuclear Safety Committee on September 14, 1990, and the unit was allowed to transfer to three element control.

On October 12, 1990, at 1401, another Unit 2 reactor scram on TSV Fast Closure occurred when a second Gould Shawmut fuse blew in the feedwater control circuitry. This event was recorded in LER 2-90-016. The involved fuse was also sent to the HE&EC center for analysis and an event recorder is currently monitoring the FW power supply circuitry. In addition, Engineering Evaluation Report (EER) 90-0262 was written to allow temporary replacement of the Gould Shawmut fuses in the Unit 2 feedwater control circuitry with Bussman Min fuses.

The draft report from the HE&EC concludes that the Gould Shawmut A25Z2 fuse was found to not exhibit any features which would be interpreted as defective or possibly responsible for the failure of this fuse. Based on limited testing and the observed features, it is thought that the submitted fuse failed due to a short duration exposure to a current in excess of 20 amps. The draft report recommended that additional testing of Gould Shawmut A25Z2 fuses be conducted to more accurately determine the failure conditions for the submitted fuse. This testing is in progress.

09:42:02

Reactor high level alarm is received (192").

This response is consistent with three element control logic. The zero indication of steam flow resulted in the RFPs increasing to maximum



# **LICENSEE EVENT REPORT (LER) TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (5)					PAGE (3)
Brunswick Steam Electric Plant Unit 2	05000324	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	04 OF 10
		90	-	008	-	02	

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

flow causing a rapid increase in water level.

09:42:05 Increased feedwater flow causes condensate pressures to drop. The "C" condensate booster pump auto starts, per design.

09:42:06 The increased feedwater flow causes a reactor power transient due to positive reactivity addition. APRMs exceed the 108% block alarm setpoint. Peak power is 110%.

The increased feed flow resulted in cooler water being injected to the vessel. The noted increase in power is consistent with an injection of cooler water.

09:42:11 Reactor high level trip setpoint (208") is reached, a trip signal is sent to the main turbine and both feedwater pumps, per design, to protect the turbines from water impingement.

Closure of the Turbine Stop Valves (TSVs) generates the reactor SCRAM signal and rod insertion begins. This is an anticipatory SCRAM designed to minimize/prevent a pressure spike upon closure of the stop valves. All four Reactor Protection System (RPS) channels also receive a trip signal from the Turbine Control Valve Fast Closure (TCVFC) circuits.

The turbine uses a generator trip which removes power to the unit auxiliary transformer (UAT). Loss of power to the UAT removes the voltage from the "2B" 4160 volt bus which supplies power to the reactor recirculation (RR) pumps. Power is lost to the RR M/G set and the RR pumps begin to coast to a stop.

09:42:22 Because feed to the vessel was secured when the feedpumps tripped, level decreased to Low Level 1 (166"). The four RPS channels detected the low level and generated a trip signal. No rod movement occurred because the rods were already inserted. PCIS group 2, 6 and 8 isolation commands were generated, per design. Valves in groups 2 and 6 closed, per design; group 8 valves were already closed and therefore did not change position.

09:42 AOG is bypassed by high flow. High SJAE discharge pressure noted.

After the RFPs tripped, condensate flow to the SJAE intercondenser and aftercooler was virtually eliminated. This prevented condensing of steam and caused the steam to be ejected into the SJAE discharge, resulting in the observed increase in flow. The increased flow and moisture from the steam resulted in the observed high SJAE discharge pressure. This was remedied by opening the SJAE minimum flow line which allowed the steam to condense.

09:42:27 In accordance with plant procedures (EOP-1, Flow Path 3), the RO transfers the mode switch from "RUN" to "SHUTDOWN". This

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Brunswick Steam Electric Plant Unit 2	DOCKET NUMBER (2) 05000324	LER NUMBER (6)				PAGE (3) 05 OF 10
		YEAR 90	-	SEQUENTIAL NUMBER 008	-	REVISION NUMBER 02

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

action creates the expected manual SCRAM signal in both RPS divisions.

Removing the mode switch from "RUN" also enables the 40% steam flow isolation instrumentation. When steam flow indication is available, the RO verifies that total steam flow is less than 40% prior to removing the mode switch from run. In this case, (ie, without steam flow indication) the operator waited an appropriate amount of time (determined by past experience) prior to moving the mode switch and successfully prevented a main steam line (Group 1) isolation.

A half Group 1 isolation command is generated on channel "A2". Individual flow signals are not recorded, therefore one cannot determine which flow instrument created the isolation command.

09:42:40/46 As the Scram Discharge Volume fills up, the high level rod block as well as the high-high levels for all four RPS sub-channels are generated, per design.

09:46:41 RCIC is started manually and begins to inject. Level decrease is slowed to about 2" per minute. Level is about 125".

During operation of the RCIC system the barometric condenser vacuum pump tripped due to an electrical fault.

09:49:17 HPCI is started manually and begins to inject, level starts to increase at about 1/2" per second. SBT is also started to support HPCI operation.

Note: A detailed review of the "ERFIS" traces revealed that the HPCI turbine stop valve opened, closed 8.5 seconds later, stayed closed 11.5 seconds and then re-opened during the HPCI startup. During this time HPCI turbine speed coasted down from approximately 3300 rpm to 1000 rpm and then ramped to rated speed. A review of the ERFIS data, system logic and operating characteristics indicated that the closure was not due to a trip signal, a mechanical overspeed or a balance chamber adjustment problem. It has been determined that the most likely cause was a momentary perturbation of the HPCI oil system pressure downstream of the oil pressure control valve during HPCI start up. This is under investigation.

In addition, a sample of the HPCI oil, taken on 8-17-90, was found to contain approximately 12% water. A previous sample, taken on 7-25-90, contained only 0.25% water. Water intrusion has been a problem in the past and is monitored. The monitoring effort has determined that a significant portion of the problem was corrected by the replacement of the steam supply valves. Since this replacement, significant water intrusion has been identified on two occasions. After this most recent intrusion, troubleshooting was performed which eliminated the possibility of a gross lube oil cooler failure. In addition, Unit 2 HPCI has been operated five times since this August water intrusion.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Brunswick Steam Electric Plant Unit 2	DOCKET NUMBER (2) 05000324	LER NUMBER (8)				PAGE (3) 06 OF 10
		YEAR 90	-	SEQUENTIAL NUMBER 008	-	REVISION NUMBER 02

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

and the in leakage resulted in less than 1% water. The exact cause of the in leakage has not been determined but an investigation is continuing. Currently this is not an operability concern.

09:49:40 Computer printout gives the appearance that "B2" channel of SDV high high level is alternating between a set and reset state. Follow-up investigation verified proper operation of both the float and thermal level sensors.

09:51:15 Rx Feedpump "A" begins to feed vessel.

09:51:20/23 Reactor level is above the Level 1 setpoint (166") and continues to increase.

09:51:42 Rx Feedpump "A" speed is decreased to stop vessel feed.

09:51:48 High reactor level alarm is reached (192").

09:51:50 HPCI is manually tripped.

09:53:42 RCIC is manually secured.

09:53:47 High level - the trip is reached (208").

09:54 RHR loop is placed in torus cooling mode. SDV vent and drain valves verified closed.

09:56 RO bypasses the SDV high-high level and resets the SCRAM.

09:57 Control rods verified full in.

09:58 RHR loop "B" is placed in torus cooling mode.

10:07 SDV "B1" resets.

10:09 SDV "B2" resets.

10:42 Buss "2B" is energized from "SAT". The RR pumps cannot be restarted because the temperature limits for restart are not satisfied. Primary cause is the partial plugging of the bottom head drain.

10:43 SDV "A2" resets.

11:03 Both HPCI and RCIC are restored to "Standby".

11:35 SDV "A1" resets.

11:49 SDV high level keylock bypass is removed.

11:57 Secured the SBTG trains.

12:05 Piping walkdowns on HPCI, RCIC, RHR and the SDV completed. No abnormalities noted.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)
Brunswick Steam Electric Plant Unit 2	05000324	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER
		90	-	008	-	02
						07 OF 10

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

## Temperature Transient Occurrence (Reference Sequence of Events 09:42:11)

On August 16 and 17, 1990, three separate transients that exceeded a 100 degree fahrenheit (F) change in reactor pressure vessel (RPV) temperature in one hour occurred. The first transient involved a cool down and the other two involved a heat up. Contributing to the first transient was a partially plugged bottom head drain line and the tripping of the recirculation pumps which allowed for stratification of the reactor coolant.

Transient Number	Temperature Deg. F		Pressure (PSIG)	
	Initial	Final	Initial	Final
1	420	285	825	650
2	110	285	0	56
3	120	250	0	30

As required by Technical Specification 3.4.6.1, General Electric (GE) was requested to perform an evaluation on the fracture toughness properties. GE Service Information Letter (SIL) 430 provides the following guidance to determine adherence to the 100 deg. F/hr requirement: use steam dome temperature (based on pressure) whenever reactor temperature is >212 deg. F and the recirculation suction temperature whenever reactor temperature is <212 deg. F. GE concluded that the 100 degree F/hr requirement limit was not exceeded.

## Possible Pin Hole Fuel Leak

In accordance with established procedures, weekly samples of the reactor coolant and off gas are analyzed for the fission products of iodine, krypton and xenon isotopes. In addition, sampling is also carried out whenever a power change of 15% or greater in one hour occurs. Sampling after the 8-16-90 SCRAM indicated a factor of ten increase in the calculated iodine dose equivalent (ie, from 4.413 E-4 to 2.984 E-3 micro curies/milliliter). Subsequent samples taken on 9-6-90 and 9-10-90 have returned to nearly the same iodine dose equivalent that existed on 8-9-90 (ie, 1.881 E-4 and 6.183 E-4 respectively). The graphic representation of the isotopic analysis indicates that a very small leak may exist because the increase has occurred in the xenon and krypton gases but the iodine has essentially remained the same. In addition, subsequent sampling shows that the total micro curie release rate has essentially not changed. If a leak exists it will manifest itself by an increase in release rate after a rod shuffle. Monitoring of the release rate will continue with Chemistry personnel working closely with Nuclear Engineering to determine the location of the leak, if it exists.

Indications of a single failure, small pin hole leak, possibly a very small end well failure, were detected after a rod shuffle on October 11, 1990. Chemistry and Nuclear Engineering personnel are continuing to work together to determine its location and expect to be able to make a determination after March 1991 when core characteristics will be more favorable for finding such a small leak.

## EVENT CAUSE

The cause of this event was failure of primary power fuse C32-F5, which supplied power to the steam flow inputs of the three element feedwater control logic. Loss of the steam flow inputs resulted in a maximum demand signal to the RFPs and a rapid increase in reactor level up to the high level turbine trip point which, in turn, caused a reactor scram on TSV position.



**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)

Brunswick Steam Electric Plant Unit 2

DOCKET  
NUMBER (2)

05000324

LER NUMBER (6)

YEAR

90

-

SEQUENTIAL  
NUMBER

008

REVISION  
NUMBER

02

PAGE (3)

08 OF 10

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

CORRECTIVE ACTIONS

Primary power fuse C32-F<sup>F</sup> and its associated circuit were evaluated. No cause for the fuse failure was determined. The fuse was replaced and the failed fuse was analyzed by the HE&EC. The draft HE&EC report indicates that the fuse failed due to an actual short duration exposure to a current in excess of 20 amps. HE&EC is continuing its investigation. The Gould Shawmut fuses in the feedwater control circuitry have been replaced temporarily by Bussman Min fuses in accordance with EER 90-0262.

The HPCI turbine stop valve cycling problem and the water intrusion into the HPCI oil are being investigated.

The cause of the RCIC barometric condenser vacuum pump electrical fault has not been determined. The pump has operated satisfactorily since this event.

The GE information provided in the evaluation of the Unit 2 cool down and heat up transients will be reviewed against current practices and procedures.

The reactor recirculation pumps will be powered from the SAT to minimize temperature transients due to loss of the UAT with the reactor vessel bottom drain clogged (a more highly probable event than the loss of the SAT).

Actions pertaining to the bottom head drain clogging have not been determined.

Monitoring of the reactor coolant and off gas release rates will continue in accordance with currently established procedures.

EVENT ASSESSMENT

The safety significance of this event is minimal. The plant responded as designed with the exception of the RCIC barometric condenser vacuum pump which is not required for the operation of RCIC.

Past similar events include LERs 2-88-018 and 1-88-023 and a subsequent event was reported in LER 2-90-016.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)  Brunswick Steam Electric Plant Unit 2	DOCKET NUMBER (2)  05000324	LER NUMBER (6)				PAGE (3)  09 OF 10
		YEAR  90	-	SEQUENTIAL NUMBER  008	-	REVISION NUMBER  02

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

LER 2-90-08, SUPPLEMENT 02, ADDITIONAL INFORMATION

The final HE&EC report on fuse C32-F5 concluded that the fuse did not exhibit defects which could be interpreted as the cause for the fuse failure. The potential short duration exposure of the fuse to a current in excess of 20 amps (referenced on pages three and eight of this LER) has not been confirmed as the cause of the event. In addition, the monitoring of the incoming power supply (referenced on page three of this LER) did not reveal a problem. The cause of the fuse failure is indeterminate. A separate analysis of the Gould Shawmut fuses is continuing as a result of the second event on October 12, 1990. That analysis is attempting to accurately determine the failure condition(s) for the submitted fuses.

An investigation into the dynamic response of the HPCI turbine oil system during HPCI starts from standby is being conducted as a result of the momentary closure of the HPCI stop valve during the HPCI start up. The desirable locations and parameters for monitoring have been identified. Pressure transducers have been purchased for additional monitoring of the pressure in the HPCI oil system during testing. A special procedure, HPCI Oil System Troubleshooting (SP-91-005), was issued, January 25, 1991, to provide authorization and control over the installation and removal of the transducers during planned HPCI operations. In addition, a special procedure is being developed to investigate the possibility that a small lube oil cooler leak exists in the Unit 2 HPCI oil system causing the observed water intrusion. Sampling of the oil for water content, and filtering if required, will continue until the water intrusion is eliminated.

GE guidance on the appropriate points for monitoring reactor vessel temperature have been incorporated into the General Plant Procedure "Unit Shutdown" and Units 1 and 2 Operating Procedures for the Residual Heat Removal System. Additionally, a project has been identified to determine what actions are required to unclog and improve the bottom head drain line on Unit 2. An X-ray of the drain line to determine the exact location of the blockage is planned.

The ongoing investigations and corrective actions will be tracked in accordance with plant procedures. A supplement to this report is not expected. Results of the analysis and possible subsequent actions will be documented and maintained on site for review.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER REG-CAT. TO COMPLY WITH THIS INFORMATION  
COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS  
MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,  
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT  
(3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Brunswick Steam Electric Plant Unit 2	DOCKET NUMBER (2) 05000324	LER NUMBER (6)				PAGE (3) 10 OF 10
		YEAR 90	-	SEQUENTIAL NUMBER 008	-	REVISION NUMBER 02

TEXT (IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 366A'S) (17)

## SYSTEM/EQUIPMENT ABBREVIATIONS & EIIIS CODES

ADS	Automatic Depressurization System	EIIS not found
CS	Core Spray	BM
DG	Diesel Generator	EK
FWLCS	Feedwater Level Control System	JK
HPCI	High Pressure Coolant Injection	BJ
PCIS	Primary Containment Isolation System	JM
RCIC	Reactor Core Isolation System	BN
RHR/LPCI	Residual Heat Removal/Low Pressure Coolant Injection	BO
RFP	Reactor Feed Pump	SJ/P
RPS	Reactor Protection System	JC
SBGT	Standby Gas Treatment System	BH
SLC	Standby Liquid Control	BR
TSV	Turbine Stop Valve	TA/ISV
SJAE	Steam Jet Air Ejector	SH/EJR

## COMPONENT EIIIS CODES

C32-R603 A-D	SB/FI
C32-FR-R607	SB/FR
C32-F5	SB/FU

## ABBREVIATIONS

EOP	Emergency Operating Procedures
GP	General Plant Operating Procedure
LL	Low Level
RO	Reactor Operator
SF	Shift Foreman