NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION (7-77) * LICENSEE EVENT REPORT
$\begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T     REPORT     L     O     0     0     2     5     4     O     0     1     1     8     3     3     0     1     2     4     3     3     0     1     2     4     3     3     9       7     8     SOURCE     60     61     DOCKET NUMBER     68     69     EVENT DATE     74     75     REPORT DATE     80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)     Image: Construction of the High, Low, and Low-Low Reactor Water Level Calibration,
o ] procedure QIS 10-1, Reactor low water level switch, LIS-1-263-58A, was found to trip
0 4 at a level 0.62 inches below the Technical Specification 3.1.A. The remaining
o 5 [ three switches in the trip logic were found to be calibrated properly.
0 6 Consequently, a Reactor scram would have occurred at +0 inches Reactor water level
0 7 and safe plant operation was not affected.
$\begin{array}{c} \hline 0 \\ 7 \\ 7 \\ 8 \end{array} \qquad \begin{array}{c} SYSTEM \\ CODE \\ 1 \\ 9 \\ 10 \end{array} \qquad \begin{array}{c} CAUSE \\ CODE \\ 1 \\ 9 \\ 10 \end{array} \qquad \begin{array}{c} CAUSE \\ CODE \\ CODE \\ 12 \\ 12 \end{array} \qquad \begin{array}{c} CAUSE \\ COMPONENT CODE \\ 13 \\ 13 \\ 13 \\ 13 \\ 13 \\ 18 \\ 19 \\ 18 \\ 19 \\ 18 \\ 19 \\ 19 \\ 15 \\ 19 \\ 15 \\ 20 \\ 16 \\ 20 \\ 16 \\ 16 \\ 10 \\ 16 \\ 10 \\ 16 \\ 10 \\ 16 \\ 10 \\ 16 \\ 10 \\ 16 \\ 10 \\ 10$
SEQUENTIAL OCCURRENCE REPORT REVISION   (17) REPORT 10 0
NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
$ \begin{bmatrix} z \\ 33 \end{bmatrix} \begin{bmatrix} z \\ 34 \end{bmatrix} \begin{bmatrix} z \\ 35 \end{bmatrix} \begin{bmatrix} z \\ 36 \end{bmatrix} \begin{bmatrix} z \\ 36 \end{bmatrix} \begin{bmatrix} 0 \\ 0 \end{bmatrix} \begin{bmatrix} 0 \\ 0 \end{bmatrix} \begin{bmatrix} 0 \\ 41 \end{bmatrix} \begin{bmatrix} 0 \\ 41 \end{bmatrix} \begin{bmatrix} 0 \\ 42 \end{bmatrix} \begin{bmatrix} 0 \\ 43 \end{bmatrix} \begin{bmatrix} 0 \\ 43 \end{bmatrix} \begin{bmatrix} 0 \\ 41 \end{bmatrix} \begin{bmatrix} 0 \\ 43 \end{bmatrix}$
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 10   The cause of this occurrence was instrument setpoint drift. Level switch LIS-1-263-
111   58-A was immediately recalibrated with an as-left trip setting of 10.88 inches and
1 4 1   7 8 9   FACILITY STATUS % POWER OTHER STATUS   30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION   32 33
1 5 E 28 0 9 9 29 NA B 31 Scheduled Surveillance   7 8 9 10 12 13 44 45 46
ACTIVITY CONTENT RELEASE OF RELEASE AMOUNT OF ACTIVITY 35 1 6 2 33 2 34 NA LOCATION OF RELEASE 36 7 8 9 10 11 44 45 80 PERSONNEL EXPOSURES 0
I <thi< th=""> I I I I</thi<>
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 10 1 9 Z (42) 10 8302040189 B30124 80
PUBLICITY ISSUED DESCRIPTION 45 PDR ADDCK 05000254 PDR DR DR DESCRIPTION 45 NRC USE ONLY
7     8     9     10     68     69     80-5       NAME OF PREPARER     A     Fubs     PHONE: 309-654-2241, ext 183     g