LICENSEE EVENT REPORT

CONTROL BLOCK:
1 I A D A C 1 2 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 1 4 57 CAT 58
CON'T SOURCE G 0 5 0 0 0 3 3 1 7 0 1 0 4 8 3 3 0 1 2 8 8 3 9 SOURCE SOUR
During normal operation surveillance testing, steam was discovered escap
ing from HV-2406, the RCIC turbine hydraulic governor valve. To effect r
epairs, RCIC steam isolation valves MO-2400 and MO-2401 were closed. Thi
s closure rendered the RCIC system inoperable. In accordance with T.S.3.
ole [5.E.2, a 7-day LCO was entered for approximately 35 1/4 hours until RCIC
was made operable. There have been no previous similar occurrences.
08
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
17 REPORT SEQUENTIAL OCCURRENCE REPORT NO. N
ACTION FUTURE SPECT SMUTDOWN HOLAS 22 ATTACHMENT PORMSUB. PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORMSUB. SUPPLIER MANUFACTURER X 19 9 9 9 25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 Steam leakage from inlet flange of HV-2406 due to gasket failure. Gasket
failure due to gasket degradation. Gasket was replaced and the RCIC syst
em inspected for leakage. No leakage was found. The RCIC system is inspe
cted monthly for steam leakage. No further corrective action is planned
1 at this time. 7 a 3 FACILITY METHOD OF
STATUS OF A STATUS OF STAT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z 33 Z 34 NA NA NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) NA AMOUNT OF A
1 7 0 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES 13
7 8 9 11 12 SECRIPTION 41
TYPE DESCRIPTION I 9 Z 42 NA
PUR LICITY SSUED DESCRIPTION (45) PDR ADDCK 05000331 NRC USE ONLY S PDR ADDCK 05000331
NAME OF PREPARER Kimuel L. Hill PHONE: 319-851-7309