

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (205) 729-0791

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 83001 Technical Specification Involved 3.5.B.7

Reported Under Technical Specification 6.7.2.b.(2) * Date Due NRC 2/6/83

Event Narrative:

Unit 1 was operating normally at 99-percent power; unit 2 was shut down for a refueling outage. Unit 3 was operating normally at 100-percent power and was the only unit affected by this event. During the performance of Surveillance Inspection 4.5.B.1.C, Residual Heat Removal System, MOV Operability, 3-FCV-74-74 (drywell containment spray isolation valve) failed to operate remotely. The valve was operated locally and the limitorque operator motor was noted to be running without subsequent valve stem movement. The valve was declared inoperable and remaining redundant modes of containment cooling were tested successfully per Surveillance Inspection 4.5.B.1.C as stipulated by Technical Specification 3.5.B.7. The operator was disassembled and found to have a broken worm shaft clutch gear. The gear was replaced and the operator reassembled. The valve was retested and performed satisfactorily. This is considered a random failure and further recurrence control is not required.

There was no effect on public health and safety. Redundant systems were available and operable.

* Previous Similar Events:

BFRO50-296/81047

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP