	LICENSEE EVENT REPORT
£24	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 3 2 5 7 0 1 1 8 8 3 8 0 2 0 1 1 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During unit refueling operations, while performing testing required by IE Bulletin
03	83-03, it was determined that two crack indications were in the heat affected zone on
0 4	the pipe side of weld B32-Recirc-28-A-15, located downstream of the A loop discharge
0 5	valve F031A. Computer analysis revealed the indications are 11 percent and 5 percent
0 6	of pipe wall thickness and appear to be one-half to three-fourths inches in length on
0 7	the pipe inside diameter circumference. This event did not affect the health and
0 8	safety of the public. Technical Specification 6.9.1.8c
7 8	SYSTEM CAUSE CODE COMPONENT CODE SUBCODE SUBCO
10	The indications are attributed to IGSCC. Corrective actions to repair these indications
11	are presently under development. Following the completion of repairs to those
1 2	indications, a supplement to this report will be submitted outlining the correct
1 3	actions taken and what actions are planned to help prevent similar reoccurrences.
1 4	9
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  H 28 0 0 0 0 29 NA CTIVITY CONTENT 12 13  METHOD OF DISCOVERY DESCRIPTION 32  LC 31 Special Testing 80
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  LOCATION OF RELEASE (36)  NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY (35)  NA  NA  80
1 7 7 8	NUMBER TYPE DESCRIPTION (39)  9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  0 0 0 0 0 NA
7 8 1 9 7 8	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2 0	PUBLICITY ISSUED DESCRIPTION 45  NRC USE ONLY
	NAME OF PREPARER M. J. Pastva, Jr. PHONE 919-457-9521