

LICENSEE EVENT REPORT

Attachment to AECM-83/0098

Page 1 of 2

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	CAT	58
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE								

CON'T

REPORT
SOURCE

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 1 1 4 8 3 8 0 2 1 1 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | From January 14 through January 21, 1983, several smoke detector zones in the

0 3 | Auxiliary Building and Control Building were found alarming and would not reset.

0 4 | The zones were deactivated and fire watches were established in accordance with

0 5 | T.S.3.3.7.9. This event had no effect on the health and safety of the public and

0 6 | did not constitute a threat to plant safety. The event is reported pursuant to

0 7 | T.S.6.9.1.13.b.

7 8 9

SYSTEM CODE A B 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE E 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 2 4 23 24 25 26		OCCURRENCE CODE 0 3 27 28 29		REPORT TYPE L 30 31		REVISION NO. 0 32									
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 23 24 25 26		ATTACHMENT SUBMITTED Y 27		NPRD-4 FORM SUB. N 28		PRIME COMP. SUPPLIER A 29		COMPONENT MANUFACTURER H 2 6 0 30 31 32 33	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Investigations revealed that there was no smoke visible in all cases. Also, there

1 1 | was no apparent cause found for any of the continuous alarms. The alarms are

1 2 | attributed to spurious actuation. One detector was replaced when it would not

1 3 | reset, and the rest were cleaned. All the detectors were functionally tested and

1 4 | returned to service. This is a final report.

7	8	9																
FACILITY STATUS			% POWER				OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	5	G	28	0	0	0	29	NA				30	A	31	Alarmed Condition			

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 Z 34 NA NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		37	Z	38
				NA

7		8		9		11		12		13	
PERSONNEL INJURIES											
NUMBER						DESCRIPTION					
1	2	0	0	0	40	NA					

7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY			(43)	8302170324 830211	
TYPE DESCRIPTION				PDR ADOCK 05000416	
1	9	2	(42)	NA	S PDR

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
[2][0] [N] (44) NA 68 69 NRC USE ONLY

NAME OF PREPARER Original signed by M. Scott Freeman

PHONE

NRC USE ONLY

017-926

SUPPLEMENTARY INFORMATION TO
LER 83-024/03 L-0

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.3.7.9
Reported Under Technical Specification: 6.9.1.13.b

Event Narrative:

The following is a compilation of multiple events of smoke detector actuation for the period from January 14 through January 21. All detectors were restored within the 14 day time limit.

<u>Zone No.</u>	<u>Location</u>	<u>LCO Duration</u>
1-15	Control Building Elevation 148	4 days 9 hours
2-7	Auxiliary Building Elevation 166	6 days 2 hours
2-17	Auxiliary Building Elevation 93	4 days 3 hours
2-4	Auxiliary Building Elevation 119	7 days 2 hours Replace detector
1-24	Control Building Elevation 189	1 day 10.5 hours