77) LICENSEE EVENT REPORT CONTROL BLOCK (PLEASE PRINT OR TYPE ALL RECUIRED INFORMATION) 1.2 LICENSEE CODE 2117 REPORT 6 0 5 0 0 0 0 2 8 0 7 0 1 1 1 4 8 3 6 0 2 0 8 8 3 9 6 0 5 0 0 0 0 2 8 0 7 0 1 1 1 4 8 3 6 0 2 0 8 8 3 9 6 EVENT DATE 74 75 REPORT DATE 80 L SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) the "C" Stear Generator Level Indication LT-1-495 With the unit at full power, drifted high. This event is contrary to T.S. Table 3.7-1 and Table 3.7-2, and is reportable in accordance with T.S.6.6.2.b.(2). The redundant channels remained : 14 operable, therefore, the health and safety of the public were not affected. 1 5 15 5 17 CODE CODE SUBCODE COMP. SUBCODE COMPONENT CODE (13 12 C (16 3.7 1 9 18 OCCURRENCE SEQUENTIAL REVISION LERIRO EVENT YEAR REPORT NO. CODE NC. 67 18 13 0 0 2 0 NUMBER 31 COMPONENT MANUFACTURER PRIME COMP. ACTION ACTION METHOD SUBMITTED NPRD EFFEC HOURS E ON PLANT FORM SUE SUPPLIER N (24) Y 3 JE X 19 Z 20 R 3 6 9 26 Z 21 01 12 L 75 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 The cause of the failure is believed to be a leak on the transmitter reference leg 10 condensate pot Root Valve. Repairs will be performed during the next outage. 11 12 14 . FACILIT METHOS OF OTHER STATUS 30 DISCOVERY DESCRIPTION (32) & POWER E 28 129 10 131 1.5 10 80 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE (36) M/A 1 6 10 PERSONNEL EXPOSURES 80 DESCRIPTION (39 TYPE NUMBER 138 37 2 010 M/A PERSONNEL INJURIES 80 DESCRIPTION 41 NUMBER 10 (40) 8302170371 830208 PDR ADOCK 05000280 12 80 LOSS OF OP DAMAGE TO FACILITY (3) Z 42 PDR N/A 8 PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY 11111111 37 / 1 1 1 58 65 80 (804) 357-3184 WAVE OF POEPLESE J. L. Wilson ------

ATTACHMENT 1 SURRY POWER STATION, UNIT NO. 1 DOCKET NO: 50-280 REPORT NO: 83-002/03L-0 EVENT DATE: 01-14-83

.

TITLE OF THE EVENT: HIGH INDICATION ON STEAM GENERATOR LEVEL INSTRUMENTATION

1. Description of the Event

On January 14, 1983, with the unit at full power, channel 2 of "C" steam generator level indication (LI-1-495) drifted $\approx 5\%$ higher than channels 1 or 3. The channel was declared inoperable and the bistables were placed in the trip mode. Since the channel failure was in the non conservative direction, the minimum degree of redundancy as required by Technical Specification Table 3.7-1 and 3.7-2 was not available. This event is contrary to Tech. Spec. 3.7.B and is reportable in accordance with T.S.6.6.2.b(2).

2. Probable Consequences and Status of Redundant Equipment

Steam Generator Level Channel 2, LI-1-495, provides protection functions. Automatic reactor trip initiation will occur when 1 of 2 channels on any steam generator indicates Low Water Level coincident with a steam flow/feed flow mismatch, or 2 of 3 Low Low Steam Generator Level. Since the redundant channels remained operable, the health and safety of the public were not affected.

3. Cause

The cause of the failure is believed to be a leak on the transmitter reference leg condensate pot Root Valve.

4. Immediate Corrective Action

The redundant channels of level instrumentation were verified operable and the bistables for LI-1-495 were placed in trip.

5. Subsequent Corrective Action

Repairs will be performed during the next cold shutdown of the unit.

6. Action Taken to Prevent Recurrence

None at this time.

7. Generic Implications

None.