



Attachment

Licensee Event Report 83-008/03L-0

During the Startup Testing Program, both control structure chlorine detectors were declared inoperable due to a failure of the constant drip feature. This is reportable per Technical Specification 6.9.1.9.b. There were no adverse consequences in that no chlorine spill occurred when the detectors were inoperable, and the Control Room Emergency Outside Air Supply System was placed in the recirculation mode.

The constant drip feature, on both chlorine detectors, failed due to contamination of the wick, preventing the electrolyte solution from dripping. The wicks were replaced and the detectors returned to the operable status. The cause of the contamination is presently under review. Upon determination of the cause of this event, appropriate corrective actions will be taken. As an interim action, a periodic preventive maintenance plan is being implemented.

Similar Licensee Event Reports: 82-073, 82-053, 82-025.