

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T | N | S | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 57 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT No

CONT

01 | R | P | T | 6 | 0 | 5 | 1 | 0 | 0 | 0 | 3 | 2 | 7 | 7 | 0 | 1 | 1 | 9 | 8 | 3 | 8 | 0 | 2 | 1 | 7 | 8 | 3 | 9
7 8 60 61 78 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | With unit 1 in mode 2 (3% power) at 1300 CST on 01/19/83, auxiliary feedwater level
03 | control valve 1-LCV-3-164 failed to operate and was declared inoperable. This required
04 | entry into action statement "a" of LCO 3.7.1.2. There was no effect upon public
05 | health and safety. There have been numerous occurrences on auxiliary feedwater level
06 | control valves, but no previous occurrences have been attributed to the failure of the
07 | pressure switches.

09 | W | B | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16
7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 8 | 3 | 11 | 12 | 0 | 0 | 7 | 13 | 0 | 3 | 14 | 15 | 16 | 17
21 22 23 24 26 27 28 29 30 31 32
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | L | 25 | D | 2 | 4 | 9
33 34 35 36 37 40 41 42 43 44 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM:UB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | Investigation revealed that pressure switch 1-PS-3-164 had failed with its contacts
11 | in the closed position which caused the valve not to open. The most probable cause
12 | for the failure of the Dual Snap Model 604 pressure switch is dirty contacts. The
13 | contacts were cleaned and calibration verified. The valve was returned to service
14 | on 01/19/83. No further action is planned at this time.

15 | C | 28 | 0 | 0 | 3 | 29 | NA | 30 | B | 31 | Operator observation
7 8 9 10 12 13 44 45 46
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12
PERSONNEL INJURIES NUMBER DESCRIPTION

19 | Z | 42 | NA | 43 | 8302280155 830217
7 8 9 10 12
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION PDR ADOCK 05000327 S PDR

20 | N | 44 | NA | 45
7 8 9 10
PUBLICITY ISSUED DESCRIPTION