

Appendix

NOTICE OF VIOLATION

Toledo Edison Company

Docket No. 50-346

As a result of the inspection conducted on December 1-30, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 4.2.1 requires that the Axial Power Imbalance be determined to be within limits once per hour when the Axial Power Imbalance alarm is inoperable and the unit is in Mode 1 at greater than 40% power.

Contrary to the above, for more than two months, the Axial Power Imbalance alarm was inoperable and the Axial Power Imbalance was not calculated hourly. Initial calibration of the alarm was not performed until more than two months of operations at greater than 40% power and no method existed for determining operability of the alarm or for alarms covered by Technical Specifications 4.1.3.1.1; 4.1.3.2.1; 4.1.3.3; 4.1.3.6; 4.1.3.9; or 4.2.4.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

\_\_\_\_\_  
Dated

\_\_\_\_\_  
C. E. Norelius, Director  
Division of Project and  
Resident Programs