## SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764 COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR. VICE PRESIDENT NUCLEAR OPERATIONS Fabruary 22, 498510. 34

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta Street, N.W. Atlanta, Georgia 30303

> SUBJECT: Virgil C. Summer Nuclear Station Docket No. 50/395 Operating License No. NPF-12 Thirty Day Written Report LER 83-006, Revision 1

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-006, Revision 1, for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into the Action Statement of Technical Specification 3.6.5.1, "Hydrogen Monitors," on January 13, 1983.

Revision 1 to this LER corrects administrative errors discovered by the Licensee. Should there be any questions, please call us at your convenience.

Very truly yours,

O. W. Dixon, Jr.

CJM:OWD:dwf/fjc Attachment

V. C. Summer cc:

T. C. Nichols, Jr.

E. C. Roberts

O. W. Dixon, Jr.

H. N. Cyrus

H. T. Babb

D. A. Nauman

M. B. Whitaker, Jr.

W. A. Williams, Jr.

O. S. Bradham

R. B. Clary

C. A. Price

A. R. Koon

G. D. Moffatt

Site QA

C. L. Ligon (NSRC)

G. J. Braddick

J. L. Skolds

J. B. Knotts, Jr.

B. A. Bursey


I&E (Washington)

Document Management Branch

INPO Records Center

NPCF

File



Mr. James P. O'Reilly LER No. 83-006, Revision 1 Page Two February 22, 1983

#### DETAILED DESCRIPTION OF EVENT

On January 13, 1983, with the Plant in Mode 1, a Common Failure alarm was received on Post Accident Hydrogen Analyzer "A". The unit was declared inoperable because of a possible heater failure in the sample compartment. The containment hydrogen monitors are required to be operable while in Modes 1 and 2 in accordance with Technical Specification 3.6.5.1.

#### PROBABLE CONSEQUENCES

No adverse consequences resulted from this event. Hydrogen Analyzer "B" remained operable during the period of time covered by this event. The satisfactory results obtained from previously performed monthly operational tests provides assurance that Hydrogen Analyzer "A" was operational up until the documented failure on January 13, 1983.

#### CAUSE(S) OF THE OCCURRENCE

The cause of Hydrogen Analyzer "A" failure was due to heat damaged wiring in the sample compartment. A temporary cover previously installed on the sample compartment was inadequately insulated. The thermostat for the compartment heaters did not detect the high temperatures present in some area; of the compartment because of the excessive heat loss through the temporary cover.

#### IMMEDIATE CORRECTIVE ACTIONS TAKEN

The hydrogen analyzer detector cell was found to be inoperable because of heat related damage to the component wiring and detector cell. A temporary cover previously installed on the heated sample compartment did not provide adequate insulation. The thermostat for the heaters failed to detect the high temperatures present in some areas of the compartment because of the excessive heat loss in the vicinity of the thermostat. The damaged wiring and detector cell were replaced, and Hydrogen Analyzer "A" was returned to operable status on January 18, 1983, upon the completion of a satisfactory operational test with the appropriate surveillance test procedure.

Mr. James P. O'Reilly LER No. 83-006, Revision 1 Page Three February 22, 1983

# IMMEDIATE CORRECTIVE ACTIONS TAKEN (Cont'd)

On February 4, 1983, Hydrogen Analyzer "A" was again removed from service in order to install a new cover and wiring (rated for 275°F environment). The components were replaced, and Hydrogen Analyzer "A" was returned to operable status on February 5, 1983, upon the completion of a satisfactory operational test with the appropriate surveillance test procedure.

### ACTION TAKEN TO PREVENT RECURRENCE

The Licensee plans no further action in regards to this event other than performance of the normal surveillance requirements.