

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | A | Y | K | R | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 9 | 7 | 0 | 1 | 1 | 9 | 8 | 3 | 8 | 0 | 2 | 1 | 8 | 8 | 3 | 9
7 8 60 61 68 69 74 75 80

02 | While in Mode 3, the Primary Vent Stack airborne radioactivity monitor f
03 | ailed. This is contrary to T.S. Table 3.3-4, section 2.6.1 a, b and c. N
04 | o releases were in progress, nor were any initiated, during the event. S
05 | team Generator Blowdown and Air Ejector monitors were functional during
06 | the event. There was no adverse effect on the public health and safety.

09 | M | C | 11 | X | 12 | Z | 13 | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16
7 8 9 10 11 12 13 18 19 20

17 | 8 | 3 | 21 | 22 | 0 | 0 | 4 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32
18 | B | 18 | F | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 37 | N | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26
33 34 35 36 37 40 41 42 43 44 47

10 | The cause of the event was frozen sample lines due to missing pipe insul
11 | ation. The repair process included replacing insulation, a Root Blower N
12 | o. 830-554-4-20 air pump and a NMC Mod. No. CRM-71 rate meter on the No
13 | ble Gas Channel. Both replacements were in kind. The monitoring system
14 | air moisture removal system is being upgraded.

15 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator Observation | 32
7 8 9 10 12 13 44 45 46

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12

19 | Z | 42 | NA | 43
7 8 9 10

20 | N | 44 | NA | 45
7 8 9 10

NA
8303010404 830218
PDR ADOCK 05000029
S PDR

NRC USE ONLY

NAME OF PREPARER: Donald A. Rice PHONE: (413) 625-6140