

NRC FORM 366  
(1-83)U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORTAPPROVED BY OMB  
3150-0011  
EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | s | c | v | c | s | l | 02 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 03 | 4 | 1 | 0 | 0 | 0 | 04 | | | 05 | | |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

01 | REPORT SOURCE | L | 02 | 0 | 5 | 0 | 0 | 0 | 3 | 9 | 5 | 07 | 0 | 1 | 1 | 2 | 8 | 3 | 08 | 0 | 2 | 2 | 2 | 8 | 3 | 09 | | |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On January 12, 1983, with the Plant in Mode 1, Fire Detector Zone DDD in

03 | the Service Water Pumphouse failed to reset during the performance of

04 | an operational test. There were no adverse consequences. An hourly fire

05 | watch patrol established within one (1) hour of the occurrence provided

06 | assurance that any fire would have been promptly discovered and extinguished.

07 |

08 |

09 | SYSTEM CODE | A | B | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | C | 13 | COMPONENT CODE | T | N | S | T | R | U | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | Z | 16 |

17 | LER/RO REPORT NUMBER | 8 | 3 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 0 | 5 | 23 | 24 | OCCURRENCE CODE | 0 | 3 | 25 | 26 | REPORT TYPE | L | 30 | 31 | REVISION NO. | 1 | 32 |

18 | ACTION TAKEN | E | 18 | FUTURE ACTION | H | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | P | 4 | 3 | 5 | 26 |

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The failure to reset was due to a grounded smoke detector. The detector

11 | head had not been properly installed in the base of the assembly after a pre-

12 | viously performed sensitivity test. The ground cleared after the head was

13 | installed properly, and the system was returned to service on January 19, 1983.

14 | Test personnel have been cautioned on the proper installation of smoke detectors.

15 | FACILITY STATUS | B | 28 | % POWER | 0 | 5 | 6 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance Test | 32 |

16 | ACTIVITY CONTENT RELEASED | Z | 33 | AMOUNT OF ACTIVITY | N/A | 34 | LOCATION OF RELEASE | N/A | 35 |

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 36 | TYPE | Z | 37 | DESCRIPTION | N/A | 38 |

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 39 | DESCRIPTION | N/A | 40 |

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 41 | DESCRIPTION | N/A | 42 |

20 | PUBLICITY ISSUED DESCRIPTION | N/A | 43 |

8303010474 830222  
PDR ADOCK 05000395  
S PDR

NAME OF PREPARER C. J. McKinney

PHONE: (803) 345-5209