## LICENSEE EVENT REPORT

-	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 3 2 5 7 0 1 1 9 8 3 8 0 2 1 8 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During unit refueling operations, routine RTGB surveillance revealed that insert/
0 3	withdrawal position and drive power indication for SRMs and IRMs was not working.
0 4	This event did not affect the health and safety of the public.
0 5	
0 6	
07	
0 8	Technical Specifications 3.3.1, 3.9.2, 6.9.1.9b
7 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
1 0	Cause Description and corrective actions (27) Control power supply fuse F13, which supplies position and drive power indication for the SRMs and IRMs, had blown. The fuse, MIN No. 10, was replaced and position and
1 2	drive power indication for the SRMs and IRMs was returned to service. A Work Request
1 3	and Authorization has been written to investigate the cause of the blown fuse.
	9 FACILITY STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5	H 28 0 0 0 0 29 NA A A 31 Operational Event
	AMOUNT OF ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35  NA LOCATION OF RELEASE 36  NA N
17	NUMBER TYPE DESCRIPTION (39) NA NA
7 8	9 11 12 13 80 PERSONNEL INJURIES NUMBER DESCRIPTION 41)
7 8	9 11 12 NA 80
1 9 7 8	LOSS OF OR DAMAGE TO FACIL TY 43  TYPE DESCRIPTION  NA  8303010486 830218  80
2 0	PUBLICITY ISSUED DESCRIPTION (45) S PDR S
	NAME OF PREPARED M. J. Pastva, Jr. PHONE 919-457-9521 a