

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | J | A | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 3 | 7 | 0 | 1 | 5 | 2 | 0 | 8 | 1 | 2 | 8 | 0 | 1 | 3 | 1 | 0 | 3 | 8 | 1 | 3 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: 10
0 2 | During normal operation, following surveillance, Residual Heat Removal Service
0 3 | Water (RHRSW) Pump 'A' discharge check valve stuck open at the completion of pump
0 4 | testing. The pump was declared inoperable when required by T.S. 3.5.B.1. Other
0 5 | RHR components were tested with satisfactory results as required by T.S. 4.5.B.2.
0 6 | No significant hazard existed.
0 7 |
0 8 |

0 9 | S | H | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | C | 15 | A | 16 |
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | 0 | 2 | 4 | 24 | 26 | 27 | 0 | 3 | 28 | 29 | L | 30 | 31 | 2 | 32 |
A | 18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | Y | 24 | A | 25 | V | 0 | 8 | 5 | 26 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 | As presented in Revision 0, inspection of the other Residual Heat Removal Service
1 1 | Water (RHRSW) and Emergency Service Water (ESW) pump discharge check valves was
1 2 | performed with the following results and corrective actions. Revision 1 attachment
1 3 | was in error; Revision 2 rectifies the errors.
1 4 |

1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance | 32

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

1 8 | 0 | 0 | 0 | 40 | NA | 41

1 9 | Z | 42 | NA | 43

2 0 | N | 44 | NA | 45 | 8303140507 830303 PDR ADDCK 05000333 PDR | NRC USE ONLY

NAME OF PREPARER: William Fernandez PHONE: (315) 342-3844

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 82-024/03L-2

PAGE 1 of 1

1. 10 RHR 14B 10/16208 (Inspected 10/15/82)

Inspected valve. Found that cotter pin was missing. No other problems. Installed stainless steel cotter pin.

2. 10 RHR 14C 10/16207 (Inspected 2/7/83)

Inspected valve. Found disc nut partially eroded away. No other problems. Replaced disc nut. Replaced carbon steel cotter pin with stainless steel.

3. 10 RHR 14D 10/16209 (Inspected 10/15/82)

Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.

4. 46 ESW 1A 46/16221 (Inspected 10/22/82)

Inspected valve. Found disc stud corroded. No other problems. Replaced carbon steel cotter pin with stainless steel. Ordered new disc.

5. 46 ESW 1B 46/16222 (Inspected 10/15/82)

Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.