

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PABVS1 200-000000-00 3411111 4 5

LICENSEE CODE 14 LICENSE NUMBER 25 LICENSE TYPE 30 CAT 58

CON'T

01 REPORT SOURCE L 605000334 7021283 8022883 9

DOCKET NUMBER 68 EVENT DATE 74 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 At 11:04 hours, on 2/12/83, main steam trip valve [TV-MS-101B] shut on

03 loss of air. This increased steam flow in the "1A" steamline, caused a

04 momentary drop in steamline pressure initiating a safety injection/reactor

05 trip. There were no safety implications to the public because all Emer-

06 gency Safeguards Features (ESF) systems functioned as designed to return

07 the plant to a stable condition. Safety injections to date: 16 operat-

08 ional and 2 pre-operational.

09 SYSTEM CODE HB 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE VAIVEX 14 COMP. SUBCODE C 15 VALVE SUBCODE D 16

17 LER/RO REPORT NUMBER 83 23 EVENT YEAR 83 24 SEQUENTIAL REPORT NO. 005 27 OCCURRENCE CODE 99 30 REPORT TYPE X 31 REVISION NO. 0 32

ACTION TAKEN B 18 FUTURE ACTION X 19 EFFECT ON PLANT A 20 SHUTDOWN METHOD C 21 HOURS 0053 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER S075 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 A sweated fitting which joins the air supply line to th line leading to

11 the actuating cylinders for [TV-MS-101B] had separated due to a possible

12 cold solder joint. The sweated fitting was repaired on 2/12/83. All

13 the fittings on the air supply lines to all three trip valves [TV-MS-

14 101A, 101B, and 101C] were leak-checked and found to be satisfactory.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY RELEASED Z 33 CONTENT OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8303140512 830228
PDR ADOCK 05000334
S PDR

NRC USE ONLY

Attachment To LER 83-005/99X
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.