

* CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	1	7	0	2	1	1	8	3	8	0	2	2	5	8	3	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While Unit 2 was in Mode 3 and Unit 3 was in Mode 5, at 0200, CREACUS Train A failed
03 to maintain the required 1/8" positive pressure in the Control Room during testing.
04 Train A was declared inoperable. Action Statement associated with LCO 3.7.5 allows
05 operations to continue for up to 7 days. At 1750, Train B failed the same test and
06 was declared inoperable. LCO 3.0.3 was invoked since LCO 3.7.5 does not address the
07 inoperability of two trains. Unit 2 was placed in Mode 5 at 2010 on 2/12/83 satisfying
08 LCO 3.0.3. Control Room habitability was not affected since normal ventilation was operable.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	S	G	E	B	P	E	N	E	T	R	X	O				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	8	3	—	0	1	0	—	0	1	T	—	0					
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	A	A	0	0	2	6	Y	N	A	X	9	9	9	9		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Failure of CREACUS to maintain the required positive pressure was due to air leakage
1 1 from Control Room boundary. Design changes were made to the fans, and new door
1 2 seals were installed. Also, a Tech. Spec. change was approved to allow for
1 3 increased fan flow and filter pressure drop. The trains were tested and declared
1 4 operable on February 21, 1983. See attachment for further information.

8 9 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 B (28) 0 0 0 (29) N/A B (31) Surveillance Testing

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY N/A 35

44

LOCATION OF RELEASE N/A 36

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	39	N/A

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	N/A

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

20		N		44		N/A		PDR		PDR		NRC USE ONLY	
----	--	---	--	----	--	-----	--	-----	--	-----	--	--------------	--

NAME OF PREPARER H.B. Ray *HBRay / DCM*

PHONE 714-492-7700

ATTACHMENT TO LER 83-010

SOUTHERN CALIFORNIA EDISON
SAN ONOFRE NUCLEAR GENERATING STATION

UNIT NO. 2, DOCKET NO. 50-362

SUPPLEMENTAL INFORMATION FOR CORRECTIVE ACTIONS

Measures to assure Control Room boundary integrity are in effect. Further measures are being developed which may include design modifications to the Control Room boundary and CREACUS and additional administrative measures to assure continued system operability. These measures, when finalized, will be reported in a revision to this LER.