

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 1
2 0 0 - 0 0 0 0 0 0 - 0 0
3 4 1 1 1 1 1
4
5

01 L
6 0 5 0 0 0 2 8 0
7 0 2 0 4 8 3
8 0 3 0 4 8 3
9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the unit at 85%, it was discovered that the latch mechanism of fire door #20
03 | had been taped over, causing the fire barrier to be inoperable. This is contrary to
04 | T.S. 3.21.G.2 and is reportable per T.S.6.6.2.b.(2). Since other fire protection
05 | systems remained operable, the health and safety of the public was not affected.
06 |
07 |
08 |

09
SYSTEM CODE A B 11
CAUSE CODE A 12
CAUSE SUBCODE E 13
COMPONENT CODE X X X X X X 14
COMP. SUBCODE Z 15
VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 18 3 21
EVENT YEAR 18 3 22
SEQUENTIAL REPORT NO. 0 0 7 24
OCCURRENCE CODE 0 3 28
REPORT TYPE L 30
REVISION NO. 0 32

ACTION TAKEN B 18
FUTURE ACTION Z 19
EFFECT ON PLANT Z 20
SHUTDOWN METHOD Z 21
HOURS 0 0 0 0 22
ATTACHMENT SUBMITTED Y 23
NPRD-FORM SUB. N 24
PRIME COMP. SUPPLIER Z 25
COMPONENT MANUFACTURER Z 9 9 9 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Construction personnel in the area had taped over the latch. The tape was
11 | removed and the door was returned to operable status.
12 |
13 |
14 |

15
FACILITY STATUS E 28
% POWER 0 8 5 29
OTHER STATUS N/A 30
METHOD OF DISCOVERY B 31
DISCOVERY DESCRIPTION O. C. Inspection 32

16
ACTIVITY CONTENT Z 32
RELEASED OF RELEASE Z 34
AMOUNT OF ACTIVITY N/A 35
LOCATION OF RELEASE N/A 36

17
PERSONNEL EXPOSURES 0 0 0 37
TYPE Z 38
DESCRIPTION N/A 39

18
PERSONNEL INJURIES 0 0 0 40
DESCRIPTION N/A 41

19
LOSS OF OR DAMAGE TO FACILITY Z 42
TYPE N/A 43

20
PUBLICITY DESCRIPTION N 44
ISSUED S
DESCRIPTION 8303150166 830304
PDR ADOCK 05000280
S PDR 45
NRC USE ONLY

NAME OF PREPARER J. L. Wilson PHONE (804) 357-3184

ATTACHMENT 1
SURRY POWER STATION, UNIT NO. 1
DOCKET NO: 50-280
REPORT NO: 83-007/03L-0
EVENT DATE: 02-04-83

TITLE OF THE EVENT: FIRE DOOR INOPERABLE

1. Description of the Event

On 02-04-83, with both units at power, it was discovered that the latching mechanism of fire door #20 (from the Emergency Switchgear Room to the Stairwell) had been taped over, causing the door to be inoperable. This is contrary to Technical Specification 3.21.G.2 and is reportable per Technical Specification 6.6.2.b.(2).

2. Probable Consequences and Status of Redundant Equipment

The integrity of fire barriers ensures that a fire in one area of the plant will be confined, or adequately retarded from spreading to adjacent areas. All other fire doors leading to the stairwell were properly latched. Since all other fire warning and suppression systems were operable during the event, the health and safety of the public were not affected.

3. Cause

Construction Personnel taped over the door latch to provide easier access to their work area. The electric latch had not been releasing properly.

4. Immediate Corrective Action

The immediate corrective action was to remove the tape from the latch, which returned the door to operable status and re-established the fire barrier.

5. Subsequent Corrective Action

The defective latch has been repaired.

6. Action Taken to Prevent Recurrence

Management of the Construction Personnel have been informed of this event and have instructed their personnel in the proper use of fire doors.

7. Generic Implications

None.