


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----|----------------|---|---|---|---|---|---|---|---|---|----|----|--------------|---|---|---|---|----|----|-----|--|----|
| 0 | 1 | N | C | B | E | P | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 | | |
| 7 | 8 | LICENSEE CODE | | | | | | 14 | 15 | LICENSE NUMBER | | | | | | | | | | 25 | 26 | LICENSE TYPE | | | | | 30 | 57 | CAT | | 58 |

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 2 0 1 8 3 8 0 3 0 3 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Routine RTGB surveillance during plant operation revealed primary containment

0 3 | atmosphere oxygen/hydrogen monitor, 2-CAC-ATH-1259, showed erratic indications of

0 4 | drywell oxygen/hydrogen concentrations. At the time, the redundant monitor,

0 5 | 2-CAC-ATH-1263, showed normal expected indications of drywell oxygen/hydrogen con-

0 6 | centrations. This event did not affect the health and safety of the public.

0 7 |

Technical Specifications 3.3.5.3, 3.6.6.4, 6.9.1.9b

| | | | | | | | | | | | | | | | | | |
|--------------|----|-----------------------|----|-----------------|----|-----------------|----|--------------|----|----------------------|----|------------------|----|----------------------|----|------------------------|----|
| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | COMP. SUBCODE | | VALVE SUBCODE | | | | | |
| S | E | E | | X | | I | N | S | T | R | U | Y | Z | | | | |
| 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | | | | |
| EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | | | | | | | | |
| 8 | 3 | | 0 | 2 | 2 | | 0 | 3 | L | | 0 | | | | | | |
| 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | | | | | | |
| ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | |
| X | X | X | Z | Z | | 0 | 0 | 0 | 0 | N | Y | N | B | 1 | 3 | 5 | |
| 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The erratic 1259 monitor indications resulted from water accumulation in the
1 1 instrument sample lines combined with the monitor RTGB instrument recorder,
1 2 2-CAC-AR-1259, timing circuit being out of adjustment. The water accumulation was
1 3 removed, the recorder was adjusted, and the 1259 monitor was calibrated and returned
1 4 to service. These type CAC monitors, Model No. F3M3, are being replaced in accordance
7 8 9 with a plant modification.

with a plant modification.

FACILITY STATUS (30) OTHER STATUS (30) METHOD OF DISCOVERY (32) DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 7 4 (29) NA A (31) Operator Surveillance

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) NA 44 45 80

7 8 9 10 11

| PERSONNEL EXPOSURES | | | | | | | | | | |
|---------------------|---|------|----|------------------|---|------|----|--|--|--|
| NUMBER | | TYPE | | DESCRIPTION (39) | | | | | | |
| 1 | 7 | G | 00 | (37) | Z | (38) | NA | | | |

| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | |
|--------------------|---|--------|---|-------------|-------|
| 1 | 8 | 0 | 0 | 0 | 40 NA |

| 8 | | 9 | | 11 | | 12 | | | |
|------|---|-------------|----|----|--|----|--|--|--|
| TYPE | | DESCRIPTION | | | | | | | |
| 1 | 9 | Z | 42 | | | | | | |

8203140310 820303

8 9 10
 PUBLICATION
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA
 S PDR ADOCK 05000324 PDR
 NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

NRC USE ONLY

1-800-645-7388