## LICENSEE EVENT REPORT

CONTROL BLOCK:
1 I A D A C 1 2 0 0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 1 1 0 57 CAT SE TYPE JO 57 CAT SE
CON'T
During normal operation, power was lost to the 'D' main steam isolation
[0]3] [ valve leakage control system (MSIV-LCS) logic. The 'D' MSIV-LCS was decl
[0]4 Lared inoperable and a 30-day LCO was entered per T.S.3.7.E.2. The 'A', 'B
[0]5 [", and 'C' MSIV-LCS were tested satisfactory. The LCO was met after appr
old Loximately 1 3/4 days when the reactor was in cold shutdown and the react
[0]7 Lor head vents were opened for a scheduled refuel outage. There has been
one previous similar occurrence with the MSIV-LCS logic (RO 82-69).
SYSTEM CAUSE CODE SUBCOOL COMPONENT CODE SUBCODE SUBCO
TO LER/RO EVENT YEAR REPORT NO. CODE TYPE NO.
ACTION FUTURE SPECT SHUTDOWN HOURS 22 ATTACHMENT NAME COMP. COMPONENT MANUFACTURER SUBMITTED FORMSUB. SUPPLIER MANUFACTURER MANUFACTURER 13 14 19 12 15 16 17 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Power lost due to fuse blown by random failure of the 'D' MSIV-LCS logic
MSIV Leakage Flow - High alarm relay B21 K2D. The relay was removed, the
[12] [ fuse was replaced, and power was returned to the MSIV-LCS logic. A desig
[1] In change is being pursued to replace the relay with a more reliable desi
I an to prevent recurrence.
STATUS  THER STATUS  OISCOVERY DESCRIPTION 32  A GOVERN DESCRIPTION 32  A GOVERN DESCRIPTION 32  A GOVERN DESCRIPTION 32  A GOVERN DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  1 6 Z 33 Z 32 NA  NA  NA  NA  NA  NA  NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  1 7 0 0 0 0 0 7 Z 38 NA  PERSONNEL INJURIES 13
NUMBER OF SCRIPTION 1
1 9 Z 42 NA 8303140428 830303
S PDR ADDCK 05000331
NAME OF PREPARED Mark E. Watson 319-851-7307