

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | B | R | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CONT  
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 1 | 1 | 1 | 5 | 8 | 1 | 5 | 0 | 2 | 1 | 8 | 8 | 2 | 9  
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With units 1 and 2 operating at 88% and 98% respectively, and unit 3 in refueling  
03 | outage, while performing SI 4.8.B.4-4 (Radwaste building exhaust vent monitoring  
04 | systems) the gaseous channel of continuous air monitor 0-RM-90-252 read downscale  
05 | during an internal calibration check of the counting ratemeter. (T.S. 3.8.B.8)  
06 | This system is common to all units. There was no danger to the health or safety  
07 | of the public, no redundant systems, and no previous similar events.

09 | M | B | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | Q | 15 | Z | 16 |  
9 10 11 12 13 14 15 16 17 18 19 20  
17 | 8 | 1 | \_\_\_\_\_ | 0 | 6 | 9 | \_\_\_\_\_ | 0 | 3 | X | \_\_\_\_\_ | 1 |  
21 22 23 24 25 26 27 28 29 30 31 32  
18 | E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | L | 25 | N | 3 | 0 | 5 |  
33 34 35 36 37 38 39 40 41 42 43 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Instrument drift. The counting ratemeter calibration on the NMC model AM-331F(BF)  
11 | continuous air monitor was performed per SI 4.8.B.4-4 and the channel returned to  
12 | service within 7 hours. This is considered a random event and no further recurrence  
13 | control is required.

15 | E | 26 | 0 | 8 | 8 | 29 | NA | B | 31 | Surveillance test. | 32

16 | Z | 33 | Z | 34 | NA | NA | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | N | 44 | NA | 45

8203080488 820217  
PDR ADOCK 05000259  
PDR

Gene Holder

NRC USE ONLY  
PHONE (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81069 R1 Technical Specification Involved 3.8.B.8

Reported Under Technical Specification 6.7.2.b(2) \* Date Due NRC N/A

Date of Occurrence 11/15/81 Time of Occurrence 1305 Unit 1, 2, and 3

Identification and Description of Occurrence:

The gaseous channel of continuous air monitor O-RM-90-252 read downscale during an internal calibration check of the counting ratemeter.

Conditions Prior to Occurrence:

Unit 1 at 88%.

Unit 2 at 99%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Chemical laboratory began sampling program.

Apparent Cause of Occurrence:

Instrument drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The counting ratemeter calibration on the NMC model AM-331F (BF) continuous air monitor was performed per SI 4.8.B.4-4 and the channel returned to service. This is considered a random event and no further recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: *J. W. [Signature]*