

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

CON'T

0	1	L	6	0	5	0	0	0	2	2	0	7	0	4	1	9	8	3	8	0	5	1	7	8	3	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a major maintenance outage while performing environmental surveillance

0 3 | testing, the 30 foot wind direction sensor azimuth alignment was found to be mis-

0 4 | aligned by 9.8 degrees, which is in violation of the Environmental Technical Speci-

0 5 | fication 3.1 in which the wind sensor is required to be calibrated for an accuracy

0 6 | of ± 5 degrees. Similar events were reported in LER 83-01 and 83-08.

0 7 |

0 8 |

0	9	Z	Z	11	B	12	C	13	I	N	S	T	R	U	14	E	15	Z	16	17	8	3	-	0	0	7	/	0	3	L	-	0	E	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	X	25	T	I	U	0	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This error is attributed to improper alignment of mounting plates when installed

1 1 | (in August 1982 during an equipment upgrade and readjusted in January 1983). Sub-

1 2 | sequently survey data used for alignment was found to be in error. The sensors have

1 3 | been readjusted, checked and found to be in compliance with the Technical Speci-

1 4 | fications.

1	5	G	28	0	0	0	29	NA	30	B	31	Technician Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20
1	6	Z	33	Z	34	NA	35	NA	36				
7	8	9	10	11	12	13	14	15	16				
1	7	0	0	0	37	Z	38	NA	39				
7	8	9	10	11	12	13	14	15	16				
1	8	0	0	0	40	NA	41						
7	8	9	10	11	12	13	14						
1	9	Z	42	NA	43								
7	8	9	10	11	12								
2	0	N	44	NA	45								
7	8	9	10	11	12								

8305270075 830517
PDR ADOCK 05000220
S PDR

NRC USE ONLY

NAME OF PREPARER Anthony Iavenditti

PHONE (315) 349-2611

LICENSEE EVENT REPORT

CONTROL BLOCK _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 4 | 1 | 9 | 8 | 3 | 8 | 0 | 5 | 1 | 7 | 8 | 3 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During a major maintenance outage while performing Environmental Surveillance
0 3 | Testing, the 200 foot wind direction sensor azimuth alignment was found to be
0 4 | misaligned by 8.6 degrees, which is in violation of the Environmental Technical
0 5 | Specification 3.1 in which the wind sensor is required to be calibrated for an
0 6 | accuracy of ± 5 degrees. Similar events were reported in LER 83-01 and 83-07.
0 7 | _____
0 8 | _____

0 9 | Z | Z | 11 | B | 12 | C | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16 |
9 10 11 12 13 18 19 20
17 | LER NO REPORT NUMBER | 8 | 3 | 21 22 | - | 0 | 0 | 8 | 23 24 26 | / | 0 | 3 | 28 29 | L | - | 0 | 32
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | X | 25 | T | 1 | 0 | 0 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | This error is attributed to improper alignment of mounting plates when installed
1 1 | (in August 1982 during an equipment upgrade). Subsequently, survey data used for
1 2 | alignment was found to be in error. The sensors have been readjusted, checked
1 3 | and found to be in compliance with the Technical Specifications.
1 4 | _____

1 5 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Technician Observation | 32
7 8 9 10 12 13 44 45 46 80

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45 80

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13 80

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12 80

1 9 | Z | 42 | NA | 43
7 8 9 11 12 80

2 0 | N | 44 | NA | 45 | _____ | NRC USE ONLY
7 8 9 10 88 89 90
NAME OF PREPARER Anthony Iavenditti PHONE (315) 349-2611

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 19, 1983

Mr. James M. Allan
Acting Regional Administrator
United States Nuclear Regulatory Comm.
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220
LER 83-07, 83-08

Dear Mr. Allan

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the following licensee event reports:

83-07, 83-08 which are being submitted in accordance with Environmental Technical Specification 3.1, the Meteorological Monitoring System shall measure parameters as prescribed by Table 3.1-1 to provide data that is representative of atmospheric conditions that exist at all gaseous effluent release points.

This report was completed in the format designated in NUREG-0262, dated July 1977.

Very truly yours

Charles V. Mangan

Charles V. Mangan
Vice President
Nuclear Engineering & Licensing

CVM/RGR/jm
Attachments (3 copies)
cc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

I ER2
/