NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (7-77)
LICENSEE EVENT REPORT
CONTROL BLOCK
0 1 C A S O S Z O O - 0 0 0 0 - 0 0 3 4 1 1 1 1 0 57 CAT 58 5 26 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 5
CON'T BEPORT L G 0 5 0 0 0 3 6 1 0 0 4 2 6 8 3 8 0 5 1 2 8 3 9 7 8 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
O 2 [At approximately 1830 with the Unit in Mode 4 and preparations in progress for Mode 3
[0]3] [entry, Shutdown Cooling System (SDCS) heat exchanger isolation valves 2HV8150,
0 4 2HV8152 and 2HV8153 could not be remotely opened from the Control Room. Since these
os valves are required to be remotely operated from the Control Room upon initiation of
ole shutdown cooling to avoid personnel radiation exposure from local operation,
[0]7] a Mode 3 restraint was imposed on the Unit. Public health and safety were not
old affected during this event. 7 8
SYSTEM CAUSE CAUSE CAUSE COMPONENT CODE COMP VALVE CODE CODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE 0 9 10 11 12 13 V A L V 0 P (4) F 15 Z (6)
Image: Seguential Report No. OCCURRENCE REPORT NO. OCCURRENCE REPORT NO. NO. Image: Seguential Report No. Image: Seguential Report No. Image: Seguential Code Type NO. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No. Image: Seguential No.
ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER LE 12 X 19 Z 20 Z 21 0 0 0 0 0 V 41 23 4 2 4 4 25 Z 9 9 9 9 9 2 26 33 34 19 35 36 21 37 40 41 23 42 43 25 44 43 25 44 47 26
The inability of the valves to remotely open was attributed to incorrect open
[1] sequence torque and limit switch settings. The incorrect settings caused the motor
on the valves to stop before the valves had come off their seats. The limit
and open sequence torque switch settings were adjusted and the valves successfully
stroke tested from the Control Room on April 26, 1983. (See attachment.)
FACILITY STATUS POWER OTHER STATUS Image: Status Offer Status Offe
ACTIVITY CONTENT RELEASED OF RELEASE ANOUNT OF ACTIVITY 35 1 6 7 8 9 33 7 34 NA PERSONNEL EXPOSURES 44 45 80
NUMBER TYPE DESCRIPTION (39) 7 8 9 2 38 NA 80 80 80 80 80
Loss of OR DAMAGE TO FACILITY (1) TYPE DESCRIPTION NA 8305270243 830512 PDR ADOCK 05000361 S PDR 80
Image: State of the s

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION P.O. BOX 128 SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY STATION MANAGER

May 12, 1983

TELEPHONE (714) 492-7200

TE-22

83-217

U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject:

Docket No. 50-361 14-day Follow-up Report Licensee Event Report No. 83-038 San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, H. B. Ray (SCE) to J. B. Martin (NRC), dated April 27, 1983

The referenced letter provided you with confirmation of our prompt notification pursuant to Section 6.9.1.12.1 of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2 involving Shutdown Cooling System (SDCS) heat exchanger isolation valves.

Pursuant to Section 6.9.1.12.i, this submittal provides the required 14-day follow-up report and a copy of Licensee Event Report (LER) 83-038 to address this event.

If there are any questions regarding the above, please contact me.

Sincerely,

Ablay

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3) R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

ATTACHMENT TO LER 83-038 SOUTHERN CALIFORNIA EDISON COMPANY SAN ONOFRE NUCLEAR GENERATING STATION UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTION

Based on this occurrence and prior problems, these valves will be included in a current Task Force investigation addressing problems associated with limit and position switches including procedures associated with their maintenance and operation. A certification program for personnel working on such limit and position switches has also been established. Additionally, as described in LER 82-170 (Docket 50-361), the SDCS valves will be replaced during the first refueling outage.

0645u