

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: 011JMF1; LICENSE NUMBER: 00000000000000000000; LICENSE TYPE: 41111111; CAT: 05

REPORT SOURCE: L; DOCKET NUMBER: 01501010348; EVENT DATE: 0170382; REPORT DATE: 07121812

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: At 0840 on 7/3/82, the "B" train chlorine detector was declared inoperable due to the detector tape not advancing. Tech. Spec. 3.3.3.6, in part, requires this chlorine detector to be operable. Tech. Spec. 3.3.3.6 action statement requirements were met. Health/Safety of the public was not affected. Similar occurrences were reported in LER 81-046/03L-0 (Unit 1) and LER 82-014/03L-0 (Unit 2). (Note: This LER is applicable to both Units 1 and 2 at Farley Nuclear Plant).

SYSTEM CODE: S; CAUSE CODE: E; CAUSE SUBCODE: B; COMPONENT CODE: INSTRU; COMP. SUBCODE: E; VALVE SUBCODE: Z; LER/RO REPORT NUMBER: 812; SEQUENTIAL REPORT NO.: 033; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: A; FUTURE ACTION: X; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRO-4 FORM SUB.: N; PRIME COMP. SUPPLIER: A; COMPONENT MANUFACTURER: X9199

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: This event was due to a sheared pin in the paper drive motor. Following the replacement of the pin, the "B" train chlorine detector was declared operable at 1527 on 7/3/82. An engineering evaluation will be performed on the control room chlorine detector reliability.

FACILITY STATUS: E; % POWER: 100; OTHER STATUS: NA; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Routine Surveillance

ACTIVITY CONTENT RELEASED OF RELEASE: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES NUMBER: 000; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES NUMBER: 000; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY TYPE: Z; DESCRIPTION: NA

PUBLICITY ISSUED DESCRIPTION: N; PDR ADDCK: 05000348; PDR: S

NAME OF PREPARER: W. G. Hairston, III

PHONE: (205) 899-5156