LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C A S 0 S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 0 4 57 CAT 58 6
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 6 1 7 0 4 1 1 8 2 8 0 7 2 0 8 2 9 3 SOURCE 60 60 60 60 60 60 60 6
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2] While in Mode 5 and operating Train B of the Control Room Emergency Air Cleanup
System to allow maintenance on Train A, Train B became inoperable when control room
old supply fan, A-206, was stopped because the suction damper closed and would not
[0]5 reopen. Had this event occurred during an accident requiring Control Room isolation
0 6 the ability to maintain Control Room pressure greater than surrounding air pressure
0 7 would have been compromised.
08
SYSTEM CODE SUBCODE SU
LER/HO EVENT YEAR REPORT NO. OCCURRENCE REPORT TYPE L OCCURRENCE CODE TYPE L O 3 L O 3 L L O 3 STATE OCCURRENCE REPORT TYPE D 3 STATE OCCUR
ACTION FUTURE COMPONENT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER W 1 2 0 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The damper closed as the result of a faulty flow controller. The flow controller
associated with the inlet damper to Fan A-206 was repaired.
13
1 4 L 7 8 9
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA B208020216 820720 PDR ADOCK 05000361 S PDR
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA NA N
NAME OF PREPARER H. B. Ray PHONE 714/492-7700 0