

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [A][L][B][R][F][1][2][0][0]-[0][0][0][0]-[0][0] [3][4][1][1][1][1] [4] [5]

CON'T REPORT SOURCE [L][6][0][5][0][0][0][2][5][9][7][0][1][0][9][8][2][8][0][7][2][2][8][2][9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0][2] During normal operation, 1 EN RMOV board (LPCI) MG set was removed from service due
[0][3] to loss of lubrication on generator coupling. (T.S. 3.9.B.13) There was no effect
[0][4] on the health or safety of the public in that the remaining 480 volt RMOV board
[0][5] MG sets and their associated loads remained operable and 1 EN RMOV board MG set
[0][6] was returned to service within LCO time limit. Previous similar events:
[0][7] BFR0-50-259/81093, 81081, 81070; 296/81011, 81069

[0][9] SYSTEM CODE [C][F] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [X] (13) COMPONENT CODE [M][E][C][F][U][N] (14) COMP SUBCODE [Z] (15) VALVE SUBCODE [Z] (16)
[17] LER/RO REPORT NUMBER [8][2] (18) EVENT YEAR [8][2] (19) SEQUENTIAL REPORT NO. [0][0][5] (20) OCCURRENCE CODE [0][3] (21) REPORT TYPE [X] (22) REVISION NO. [1]
ACTION TAKEN [A] (23) FUTURE ACTION [X] (24) EFFECT ON PLANT [Z] (25) SHUTDOWN METHOD [Z] (26) HOURS [0][0][0][0] (27) ATTACHMENT SUBMITTED [Y] (28) NPR-4 FORM SUB [Y] (29) PRIME COMP. SUPPLIER [L] (30) COMPONENT MANUFACTURER [W][0][1][6] (31)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1][0] Inadequate lubrication due to change of consistency of lubricant (drying out) and
[1][1] loss of lubricant. The Waldron 2-1/2 inch coupling was repacked with new grease
[1][2] after removing dried out grease. An effort is being made to obtain improved
[1][3] couplings. Periodic inspection and relubrication will be performed until
[1][4] replacement coupling is obtained.

[1][5] FACILITY STATUS [E] (28) % POWER [1][0][0] (29) OTHER STATUS NA (30) METHOD OF DISCOVERY [A] (31) DISCOVERY DESCRIPTION Operator observed (32)
[1][6] ACTIVITY CONTENT [Z] (33) RELEASED OF RELEASE [Z] (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)
[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION NA (39)
[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION NA (41)
[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION NA (43)
[2][0] PUBLICITY ISSUED [N] (44) DESCRIPTION NA (45)

GPO 817-426

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 82005 R1 Technical Specification Involved 3.9.B.13

Reported Under Technical Specification 6.7.2.b.(2) " Date Due NRC _____

Date of Occurrence 1/9/82 Time of Occurrence 1037 Unit 1

Identification and Description of Occurrence:

1 EN RMOV board (LPCI) MG set was removed from service due to loss of lubricant on generator coupling

Conditions Prior to Occurrence:

Unit 1 at 100%

Unit 2 at 0%

Unit 3 in refueling outage

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe _____

NONE

Apparent Cause of Occurrence:

Inadequate lubrication due to change of consistency of lubricant (drying out) and loss of lubricant.

Analysis of Occurrence:

There was no effect on the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action: The Waldron 2-1/2 inch coupling was repacked with new grease after removing the dried out grease. An effort is being made to obtain improved shaft couplings. Periodic inspection of couplings for lubricant leakage and relubrication will continue until improved couplings are obtained and installed. This corrective action applies to LER's listed under Failure Data.

Failure Data: BFRO-50-259/81093, 81081, 81070; 296/81011, 81069

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

Revised *J. J. [Signature]*