

LICENSEE EVENT REPORT

UPDATE REPORT

PREVIOUS REPORT DATE: 8/10/82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: _____ (1)

0 1 | I | L | D | R | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 7 | 0 | 7 | 2 | 3 | 8 | 2 | 8 | 1 | 1 | 1 | 6 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a normal startup of the unit, the APRM Gain Adjustment Factor (AGAF) for APRM's
0 3 | 2 and 3 had exceeded 1.02. An Instrument Mechanic (I.M.) was called to make adjustments
0 4 | per DIS 700-17 (T.S. Table 3.1). Prior to the arrival of the I.M., the AGAF continued to
0 5 | change until they exceeded 1.03, at which time the NSO took a 1/2 scram on channel "A"
0 6 | per DOS 500-6. The safety significance was minimal since channel "A" was placed in the
0 7 | tripped position and channel "B" was still operable. Previous occurrence reported by
0 8 | R.O. 81-32 on Docket 50-237.

0 9 | SYSTEM CODE | I | C | 11 | CAUSE CODE | D | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | Q | 15 | VALVE SUBCODE | Z | 16
9 10 11 12 13 18 19 20
 LER/RO REPORT NUMBER | EVENT YEAR | 8 | 2 | 17 | SEQUENTIAL REPORT NO. | 0 | 3 | 6 | 24 | OCCURRENCE CODE | 0 | 3 | 28 | REPORT TYPE | X | 30 | REVISION NO. | 1 | 32
21 22 23 24 26 27 28 29 30 31 32
 ACTION TAKEN | E | 18 | FUTURE ACTION | G | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | G | 0 | 8 | 0 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Cause is attributed to a procedural deficiency. Immediate corrective action was to make
1 1 | the necessary APRM gain adjustments. Long term action will be to modify the start-up/
1 2 | shutdown procedures DGP 1-1, 1-3, 2-1, 2-4 and to have an Instrument Mechanic available
1 3 | during reactor start-up or shutdown which would allow more frequent APRM gain adjustments.

1 5 | FACILITY STATUS | C | 28 | % POWER | 0 | 3 | 8 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32
8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36
8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES | NUMBER | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39
8 9 10 11 12 13 80

1 3 | PERSONNEL INJURIES | NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41 | 8212290345 821116
8 9 11 12 13 80 PDR ADOCK 05000237
8 9 11 12 13 80 S PDR

1 9 | LOSS OF OR DAMAGE TO FACILITY | TYPE | Z | 42 | DESCRIPTION | N/A | 43
8 9 10 11 12 80

1 0 | PUBLICITY | ISSUED | N | 44 | DESCRIPTION | N/A | 45 | NRC USE ONLY
8 9 10 80

NAME OF PREPARER: B. A. Schroeder PHONE: 815-942-2920, X-422

SUPPLEMENT TO DVR

DVR NO.				
STA	UNIT.	YEAR	NO.	
D - 12	- 2	- 82	- 54	

PART 1	TITLE OF EVENT	OCCURRED	
	APRM's 2 and 3 Hi Gains	7/23/82	2152
		DATE	TIME
	REASON FOR SUPPLEMENTAL REPORT		
	To update the cause and corrective action for the gains which had exceeded 1.03.		
PART 2			
	ACCEPTANCE BY STATION REVIEW	<u>J. Brune</u>	<u>John A. Almon</u>
	DATE	<u>12/8/82</u>	<u>12/17/82</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Scott</u>	<u>12/21/82</u>
		STATION SUPERINTENDENT	DATE