

CONTROL BLOCK _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | M | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

CONT

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 9 | 7 | 0 | 4 | 3 | 0 | 8 | 3 | 9 | 0 | 5 | 2 | 7 | 8 | 3 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in Mode 3, performance of a reactor coolant system (NC) leakage calcula-
0 3 | tion determined that the unidentified leakage was greater than 1 GPM. This vio-
0 4 | lates T.S.3.4.6.2 which is reportable pursuant to T.S.6.9.1.11(d) and similar
0 5 | to RO-369/81-132. The leakage was well within the capability of the charging
0 6 | pumps to maintain pressurizer level, and the leakage was contained with tempo-
0 7 | rary hoses that directed the water to the liquid waste monitor and disposal
0 8 | system. Health and safety of the public were unaffected.

0 9 | C | B | 11 | E | 12 | X | 13 | V | A | L | V | E | X | 14 | E | 15 | X | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33
17 | 8 | 3 | 21 | 22 | 0 | 2 | 6 | 23 | 24 | 0 | 3 | 25 | 26 | L | 27 | 28 | 29 | 30 | 31 | 0 | 32
18 | X | 19 | Z | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | N | 24 | N | 25 | L | 26 | W | 0 | 3 | 0 | 27
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Investigation revealed this was caused by leakage past the bonnet seal ring on
1 1 | valves 1NC-18 (RTD manifold loop D return to NC loop 4)(0.3 GPM) and 1NV-239
1 2 | (centrifugal charging pumps discharge control isolation)(0.2 GPM). The valves
1 3 | (3" Walworth hand operated gate valves) were sealed with furmanite. Unidentified
1 4 | leakage was then determined to be 0.76 GPM.

1 5 | X | 28 | 0 | 0 | 0 | 29 | Mode 3 | B | 31 | Routine Surveillance
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

1 8 | 0 | 0 | 0 | 40 | N/A | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

1 9 | Z | 42 | N/A | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

2 0 | N | 44 | N/A | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

NAME OF PREPARER Phillip B. Nardoci PHONE: (704)373-7432

8306130448 830527
PDR ADOCK 05000369
S PDR

IE22

IE 22
11

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

May 27, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

83 JUN 7 9:26
USNRC REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-26. This report concerns T.S. 3.4.6.2, "Reactor coolant system leakage shall be limited to: ...b. 1 GPM unidentified leakage,...". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

OFFICIAL COPY

IO 22

||