

### LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	I	L	D	R	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1													
7	8	9	14					15					25					26					28					30							
7		8		9		14					15					25					26					28					30				

01	L	0	5	0	0	0	2	4	9	0	2	1	2	8	3	0	2	2	4	8	3																						
7	8	9							14							15							25							26							30						
7		8		9		14							15							25							26							30									

#### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 | During normal operations while performing DOS 1400-1, Core Spray Pump Test, core

03 | spray pump 1401-3A failed to start (T.S. 3.5.A.1.). There was no effect on public

04 | health or safety. This event is of minimal safety significance since the other core

05 | spray loop and remaining ECCS were operable. First occurrence of this type at

06 | Dresden.

07 |

08 |

09	S	F	A	X	C	K	T	B	R	K	E	Z	8	3	0	0	8	0	1	T	0	X	F	Z	Z	0	0	0	0	Y	Y	N	G	0	8	0							
7	8	9	11	12	13					14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

#### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 | Cause of event was due to the circuit breaker recharging motor toggle switch being

11 | inadvertently put in the "off" position. The switch was put in the "on" position,

12 | pump was started and system operability surveillance completed successfully. A PRO

13 | investigation has been initiated to determine if further corrective action is re-

14 | quired. Switch barriers will be installed to prevent recurrence (W.R. D26051).

15	E	0	9	8	N/A	B	Surveillance Testing
7	8	9	10	11	12	13	14
7		8		9		14	
16	Z	Z	N/A	N/A			
7	8	9	10	11	12		
7		8		9			
17	0	0	0	Z	N/A		
7	8	9	10	11	12		
7		8		9			
18	0	0	0	N/A			
7	8	9	10	11	12		
7		8		9			
19	Z	N/A					
7	8	9					
20	N						
7	8	9					

8303080147 830224  
PDR ADOCK 05000249  
S PDR

A. N. Anandappa

815-942-2920, X-421

NAME OF PREPARER

PHONE:

NRC USE ONLY

ATTACHMENT TO LICENSEE EVENT REPORT 83-08/01T-0

COMMONWEALTH EDISON COMPANY (CWE)

DRESDEN UNIT 3 (ILDRS-3)

DOCKET # 050-249

During normal operations, while performing DOS 1400-1, Core Spray System Pump Test, core spray pump 1401-3A failed to start. The surveillance was performed because the 2/3 diesel generator was out of service for an annual inspection. The system was declared inoperable and a GSEP Unusual Event was declared (T.S.3.5.A.1.). There was no effect on public health or safety. This event is of minimal safety significance since the remaining ECCS were operable. First occurrence of this type at Dresden.

The cause of the event was due to the circuit breaker closing springs not being charged. The recharging motor toggle switch was inadvertently put in the "off" position which prevented the circuit breaker from closing to energize the pump motor. The toggle switch was put in the "on" position and the recharging motor energized. The pump was then started and the system operability surveillance completed successfully. Barriers over all emergency system circuit breaker toggle switches will be installed to prevent inadvertent operation of the switch (W.R. D26051). A PRO investigation has been initiated to determine if further corrective action is required.