LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	G A E I H 2 2 0 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUP BER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 6 6 0 0 2 1 0 8 3 8 0 3 1 0 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	While performing the shift "SURVEILLANCE CHECKS" procedure, the drywell/
0 3	torus temperature recorder was found inoperable. This event is contrary
0 4	to Tech. Specs. Table 3.3.6.4-1, Items 4 and 7. The redundant drywell/
0 5	torus temperature recorder remained operable. Plant operation was placed
0 6	in a 30-day LCO as per Tech. Specs. 3.3.6.4, ACTION a. The health and
0 7	safety of the public were not affected by this non-repetitive event.
08	80
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 1 1 1
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 23 N 25 L 1 3 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The component failed due to internal failed parts. All failed parts were
11	replaced. The instrument was then recalibrated and functionally tested
[1]2	satisfactorily as per the "LEEDS AND NORTHRUP SPEEDOMAX 165 AND 250 MUL-
13	TIPOINT RECORDER RTD INPUT" procedure. The recorder was returned to
7 8	service on 2/11/83.
1 5	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 LE 28 0 6 9 29 NA LB 3 Shift Surveillance Checks
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA LOCATION OF RELEASE 36 PERSONNEL EXPOSURES 44 45
17	NUMBER TYPE DESCRIPTION (39)
1 8	PERSONNEL INJURIES 13 8303210419 830310 80 10 10 10 10 10 10
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
7 . 8	9 10 PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
7 8	NA 68 69 80 3
	NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851