NRC FORM 366

U. S. NUCLEAR REGULATORY COMMISSION

(1-11)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1	M I P A L 1 3 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58 5
CON'T	SOURCE
0 2	LEE 82-044 discusses a potential overload condition with MCC-1 and MCC-2
0 3	[feeder breakers and cables when H2 recombiners are loaded. At 2046, on]
0 4	June 3, 1983, the H recombiners were simultaneously loaded to their
0 5	respective MCC for routine surveillance testing contrary to a plant Stan-
0 6	ding Order (SO) which states that the H2 recombiners will be operated
0 7	separately. The surveillance was successfully completed at 2325 on June 3.
0 8	Reportable per TS 6.9.2.a(6). No threat to public health/safety existed.
0 9	SYSTEM CAUSE COMPONENT CODE SUBCODE SU
	SEQUENTIAL REPORT CODE TYPE NO.
	ACTION FUTURE OF FECT SHUTDOWN HOURS 22 ATTACHMENT NPRD4 PRIME COMP. COMPONENT MANUFACTURER X 18 G 19 Z 20 Z 21 0 0 0 0 0 0 0 0 0
10	Cause attributed to an inadequate surv proc which stated that the test
11	Lould indeed be performed simultaneously. An SE was standing SS watch and
1 2	[did not recall the SO prior to initiation of the test. The surv proc will]
1 3	be revised to prohibit simultaneous testing of H2 recombiners. Review
7 8	reqmts for SOs will be expanded to include all SROs who may stand SS watch
	FACILITY STATUS N POWER OTHER STATUS OTHER STATUS NA DISCOVERY DESCRIPTION (32) NA DISCOVERY DESCRIPTION (32) ROutine review
	CCTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA NA LOCATION OF RELEASE 36
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 80
1 9	Z 42 NA
20	PUBLICITY ISSUED DESCRIPTION 45 NA
7 8	9 10



General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

June 17, 1983

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 5C-255 - LICENSE DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 83-39 (H₂ RECOMBINERS TESTED SIMULTANEOUSLY)

On the reverse please find Licensee Event Report 83-39 (H_2 Recombiners Tested Simultaneously which is reportable to the NRC per Technical Specification 6.9.2.a(6).

Brian D Johnson

Staff Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Palisades

JUN 2 0 1983

11 (E 2)