

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | S | L | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CON'T

0 1 | R | S | 0 | 5 | 0 | 0 | 0 | 3 | 8 | 9 | 7 | 0 | 5 | 2 | 0 | 8 | 3 | 3 | 0 | 6 | 2 | 0 | 8 | 3 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While leak testing the escape airlock per T.S. 4.6.1.3.b, a 0.157 La  
0 3 | leakrate was detected. Door equalizing valves were leaking at 0.032 La  
0 4 | (inner) and 0.123 La (outer). Total leakage was reduced to 0.0014 La  
0 5 | within two hours. Reactor had not been critical. Health and safety of  
0 6 | the public was not affected. This is the first event of this type.

0 9 | S | A | 11 | E | 12 | X | 13 | P | E | N | E | T | R | 14 | A | 15 | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 | LER/RO REPORT NUMBER | 8 | 3 | 21 | 22 | 0 | 1 | 3 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32 |  
18 | ACTION TAKEN | E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 37 | N | 23 | N | 24 | A | 25 | C | 3 | 1 | 0 | 26 |  
19 | FUTURE ACTION |  
20 | EFFECT ON PLANT |  
21 | SHUTDOWN METHOD |  
22 | HOURS |  
23 | ATTACHMENT SUBMITTED |  
24 | NRC-4 FORM SUB. |  
25 | PRIME COMP SUPPLIER |  
26 | COMPONENT MANUFACTURER |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Linkages for the inner and outer door equalizing valves were found to be  
1 1 | slightly out of adjustment and were readjusted. Doors have been used  
1 2 | extensively. Adjustments were made within two hours and the airlock  
1 3 | passed specifications.

1 5 | B | 23 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Test Observation | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | Z | 42 | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | N | 44 | NA | 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER B. Parks PHONE 305-465-3550



June 20, 1983  
PNS-LI-83-431-1

83 JUN 23 A10: 36

USNRC REGION I  
ATLANTA, GEORGIA

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-13

ST. LUCIF UNIT 2

DATE OF OCCURRENCE: MAY 20, 1983

TECHNICAL SPECIFICATION 4.6.1.3.b

CONTAINMENT AIR LOCK

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification on the subject occurrence.

Very truly yours,

*J. Williams*  
J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

OFFICIAL COPY

Te 22

11

PEOPLE... SERVING PEOPLE