

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 PASES1 200-000000-0003 411111 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58CON'T
01 REPORT SOURCE L 6 05000387 7 022883 8 032183 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in the Startup Test Program at 89% power, the "B" Diesel Generator failed

03 to start in the course of a monthly surveillance (SO-24-001B). Per Technical

04 Specification 3.8.1.1, the AC electrical power sources were verified and the

05 other 3 Diesel Generators were demonstrated operable. There were no consequent-

06 ial effects on the public health and safety. The failed component was in the

07 confines of the manual start circuitry. The "B" Diesel Generator was reworked

08 and returned to operable status the same day.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E E 11 E 12 G 13 I N S T R U 14 Y 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 LER/RO REPORT NUMBER 83 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPSD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
C 18 Z 19 Z 20 Z 21 00000 N 23 N 24 A 25 A 1 2 1 1
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The "B" Diesel Generator failed to successfully start due to a failed subcom-

11 ponent in the speed sensing circuit. This is one of the trip devices that are

12 in the manual start circuitry, but not in the Emergency/LOCA start circuitry.

13 The device, ST-03497B/1 (Airpax Frequency to Voltage Converter) was replaced

14 in entirety and recalibrated. This is a non-valid test per Reg Guide 1.108 Rev 1.

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
B 28 089 29 n/a B 31 surveillance testing
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 n/a n/a
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
000 37 Z 38 n/a
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
000 40 n/a
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 n/a
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED DESCRIPTION 45
N 44 n/a
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Jon T. Todd

PHONE (717) 542-2181 X3524

8304050277 830321
PDR ADOCK 05000387
S PDR

NRC USE ONLY