

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A S E S I 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 [] [] 5
7 8 9 14 15 25 26 30 37 38 39

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 8 7 7 0 4 1 4 8 3 8 0 5 1 3 8 3 9
7 8 50 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in an extended shutdown (outage) a Local Leak Rate Test was performed on
0 3 the 'C' Main Steam Line. The 'C' LLRT was in excess of the allowable value in
0 4 Technical Specification 3.6.1.2(c). The excessive leakage was confined to the
0 5 inboard MSIV. There were no consequential effects to the public health & safety.
0 6
0 7
0 8

0 9 SYSTEM CODE C D 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE F 15 VALVE SUBCODE D 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER 8 3 21 EVENT YEAR 22 SHUTDOWN METHOD Z 23 HOURS 0 0 0 0 24 ATTACHMENT SUBMITTED N 25 NPRD-4 FORM SUB. N 26 PRIME COMP. SUPPLIER N 27 COMPONENT MANUFACTURER A 5 8 5 28
18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 N 25 A 5 8 5 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The inboard MSIV was reworked. Normal lapping was performed on the valve disc
1 1 and seat. No deep cuts or score marks were identified on the seat or disc.
1 2 The valve was retested and successfully passed the LLRT.
1 3
1 4

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Testing - LLRT 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUED DESCRIPTION N 44 8306010068 830513 PDR ADOCK 05000387 S PDR
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER Jon T. Todd PHONE (717) 542-2181 X3240



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

May 13, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-064/03L-0
ER 100450 FILE 841-23
PLA-1663

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

Attached please find a copy of Licensee Event Report No. 83-064/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that during the performance of a Local Leak Rate Test on the Main Steam Line Isolation Valves the allowable leakage was exceeded.

H.W. Keiser
Superintendent of Plant-Susquehanna

JTT/pjg

cc: Director of Nuclear Reactor Regulation
Attention: Mr. A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

G.G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

IE 22
||