

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	1	7	0	8	0	3	8	3	8	0	8	1	7	8	3	9
60	61	DOCKET NUMBER					66	68	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation, while conducting surveillance testing, it was f  
03 | ound that the RCIC discharge pressure indicator was not indicating prope  
04 | rly. Since the surveillance test could not be completed due to this prob  
05 | lem, RCIC was declared inoperable. A 7 day LCO was declared IAW T.S. 3.5  
06 | .E.2. While testing redundant systems, test of HPCI could not be complet  
07 | ed (See LER 83-028). ADS, CS, and LPCI were proven operable. No effect o  
08 | n health and safety of public. No previous similar occurrences.

SYSTEM CODE C E 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE T 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 3 21		SEQUENTIAL REPORT NO. 0 2 7 24		OCCURRENCE CODE 0 3 28		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRO-4 FORM 308 N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The pressure transmitter for the faulty indication was out of calibration.

11 | In. The transmitter was calibrated and the surveillance testing of the RC

12 | IC completed satisfactorily on 8/3.

FACILITY STATUS (1) 5 (E) (2) 9 (6) (29) NA  
 % POWER  
 OTHER STATUS (30)  
 METHOD OF DISCOVERY (B) (31) Routine Testing  
 DISCOVERY DESCRIPTION (32)  
 ACTIVITY CONTENT  
 RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) NA  
 AMOUNT OF ACTIVITY (35)  
 LOCATION OF RELEASE (36)  
 PERSONNEL EXPOSURES  
 NUMBER TYPE DESCRIPTION (37) (Z) (38) NA  
 PERSONNEL INJURIES  
 NUMBER DESCRIPTION (39) (0) (0) (0) (40) NA  
 LOSS OF OR DAMAGE TO FACILITY  
 TYPE DESCRIPTION (41) (Z) (42) NA  
 PUBLICITY  
 ISSUED DESCRIPTION (43) (N) (44) NA  
 8308260046 830817  
 PDR ADOCK 05000331  
 S PDR  
 NRC USE ONLY

NAME OF PREPARER Daniel R. Kibler

PHONE: 319-851-7306

Iowa Electric Light and Power Company

August 17, 1983  
DAEC-83-675

Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Duane Arnold Energy Center  
Docket No. 50-331  
Op. License DPR-49  
Licensee Event Report No. 83-027  
(30-day)

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications, Section 6.11.2.b(2), and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report.

Very truly yours,

*BR York for*

Daniel L. Mineck  
Plant Superintendent - Nuclear  
Duane Arnold Energy Center

DLM/DRK/pf

attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector - DAEC

File A-118a

AUG 19 1983