

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F I L S L I S 2 0 0 1 - 0 0 1 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
 0 1 R 0 5 0 0 0 3 8 9 0 7 1 2 8 3 0 8 1 7 8 3 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 Several times during startup operations CEA #54 and CEA #17 slipped
 0 3 greater than 15 inches from their groups during CEA withdrawal. CEA #54
 0 4 finally dropped to the core bottom. This is contrary to T.S. 3.1.3.1.
 0 5 The CEAs were returned to their respective groups within 1 hour. The
 0 6 health and safety of the public were not affected by this event. This
 0 7 is the second event of this type. (See 389-83-23.)
 0 8
 0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP TUB CODE VALVE SUBCODE
R I B X Z C R I B R I V I E L Z
 9 10 11 12 13 14 15 16 17 18 19 20

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 3 8 0 3 L 0
 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFORM FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
Z Z Z Z 0 0 0 0 N N N C 4 9 0
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 Instrument and control personnel were contacted and a subsequent
 1 1 investigation was conducted. The cause of these events is unknown. All
 1 2 CEAs have operated normally since these events.
 1 3
 1 4

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
0 0 0 NA A Operator Observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
4 33 34 NA NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PUBLICITY ISSUED DESCRIPTION
N NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

NAME OF PREPARER T. S. Rotella PHONE 465-3550

USNRC REGION II
ATLANTA, GEORGIA

83 AUG 23 A9:48



August 17, 1983
PNS-LI-83-558-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 50-389-83-38

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: JULY 12, 1983

TECHNICAL SPECIFICATION 3.1.3.1

CEA POSITION

The attached Licensee Event Report has been inadvertently submitted previously on August 11, 1983 as 389-83-35.

Please find attached the Report with a corrected sequential number.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", written in a cursive style.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/JEM/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

16-22